



**APPROVED**  
DEC 17 1963  
E. G. HUBBLE  
ACTING DISTRICT ENGINEER

OFFICE COPY

(SUBMIT IN TRIPLICATE)

UNITED STATES

DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

Budget Bureau No. 42-00000  
Form Approved.

Land Office **New Mexico**

Lease No. **0 1130 B**

Unit \_\_\_\_\_

DEC 11 1963

# SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	<b>X</b>
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 6, 1963

Well No. **1** is located **760** ft. from **[N]** line and **560** ft. from **[E]** line of sec. **30**  
**NE 1/4** **30** **20 S** **34 E** **NM**  
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
**TEAS** **LEA** **NEW MEXICO**  
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3680** ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

On October 18, 1963 well was P & A in the following manner. Rods and pump and tubing removed from well. All other casing left in hole. Spotted 50 sacks Incore Regular, 2% CaCl<sub>2</sub> from TD 3526. Pulled up hole, WOC two hrs. and tagged cement plug with Howco wire line @ 3054. 75 sx plug from 3050 Regular 50:50 Pozmix 10% gel, pulled 25 jnts. tubing and cemented with 100 sx Regular 50:50 Pozmix 10% gel. Pulled up 33 jts. and cemented 5 sx Incore Regular 2% CaCl<sub>2</sub> WOC two hrs. tagged cement with Howco wire line. Spotted 10# mud top cement and circulated to surface. Spotted 25 sx plug in surface. Placed dry hole marker and sign. Cleaned and levelled location. Now ready for inspection.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **GACKLE DRILLING COMPANY**  
**P. O. Box 430**  
 Address **Hobbs, New Mexico**

**R. F. MONTGOMERY**

By **R. F. Montgomery**  
 Title **OPERATOR Agent**