40 OF COPIES RECEIVED		Form C-	
DISTRIBUTION	MURRE OFFICE OF A	Superse	
SANTAFE	HIGHES OFFICE O. B.	SSION C-102 as	
FILE			
U.S.G.S.	Jun 7 11 26 AM 368	5a. Indicate	
LAND OFFICE		State	
OPERATOR		5. State Oil	
•	DDV NOTICES AND DEPOSITS ON NET		
SUNI	DRY NOTICES AND REPORTS ON WELLS		
(DO NOT USE THIS FORM FOR	DRY NOTICES AND REPORTS ON WELLS PROPOSALS TO BRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. CATION FOR PERMIT —" (FORM C-101) FOR SUCH PROPOSALS.)		
(DO NOT USE THIS FORM FOR USE "APPLICATION OF USE	DRY NOTICES AND REPORTS ON WELLS PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. CATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.) OTHER-	7. Unit Agre	
1. OIL GAS T		7. Unit Agra East Pe	

3 VI CONTES RECEIVED		Form C-103
DISTRIBUTION	HUNGRE OFFICE OF	Supersedes Old
SANTA FE	HIDEBS OFFICE O. C. NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE		□11001148 1-1-03
U.S.G.S.	Jun 7 11 25 AN 368	5a. Indicate Type of Lease
LAND OFFICE		State Fee. X
OPERATOR	7	5, State Oil & Gas Lease No.
	_	
SUNE (DO NOT USE THIS FORM FOR E USE "APPLIC	DRY NOTICES AND REPORTS ON WELLS PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. ATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)	
1.		7. Unit Agreement Name
WELL X WELL	OTHER-	From Board O. W.
2. Name of Operator		8. Farm or Lease Name
Shell Oil Company (Was	atom Dividadon)	
Shell Oil Company (We:	areth mr. Arathur,	East Pearl Queen Unit
Doct Office Des 1500	W 11 1 M 70701	
Post Office Box 1509, 4. Location of Well	Midiand, Texas /9/III	10. Field and Pool, or Wildcat
		I
UNIT LETTER,	1980 FEET FROM THE South LINE AND 660 FEET FR	om Pearl Queen
THE East LINE, SEC	TION 28 TOWNSHIP 19-S RANGE 35-E NMP	M/M/M/M/M/M/M/M
mmmmm		
	15, Elevation (Show whether DF, RT, GR, etc.)	12. County
	3724' DF	100
Check	Appropriate Box To Indicate Nature of Notice, Report or C	
NOTICE OF	11/7	NT REPORT OF:
	30032302	KEI OKI OF.
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	A
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	ALTERING CASING
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
	OTHER	
OTHER	OTHER	
7. Describe Proposed or Completed	Operations (Clearly state all pertinent details, and give pertinent dates, includi	ng estimated date of starting any proposed
work) SEE RULE 1103.		o seemed and of seemeng any proposed
1. Pulled production	equipment.	
	acker and set at 4753'.	
	IIIA and IIIB perforations.	
4. Treated below pact	ker with 2000 gallons 15% NE Acid and 750 barrel	s hot fresh
water treated with	h one gallon per 1000 gallons LST-5.	o not itedii
5. Treated shove nect	ker and via casing annulus with 2000 gallons 15%	MP And J c 3
750 harrele hor fo	resh water treated with one gallon per 1000 gall	NE ACIG ANG
6. Pumped remaining	acid and 375 BW at 3500 psi.	ons Lol-o.
7. Pulled tubing and	mediam we colou psi.	
8. Ran 156 joints 2 1	1/2", EUE, 8rd, J-55 tubing, hung at 4908'.	
	18' RWAC Sargent pump.	
Placed on product;		
1. In 24 hours pumped	1 132 BO + 271 BW.	
- -		
panpor		

18. I hereby certify that the info Original Signed By N. W. Harrison	rmation above is true and complet	te to the best of my knowledge and belief.	
SIGNED	N.W. Harrison	TITLE Staff Exploitation Engineer	DATE June 6, 1968
APPROVED BY JOHN W		TITLE	DATE