STATE OF ILL WIMEXICO ENERGY AND MINERALS DEPARTMENT.

B. 42 (22-12 ALCOTE)	OIL CONSERVATION DIVISION	
DISTRIBUTION	P. O. BOX 2088	Form C-103
JANTA PE	SANTA FE, NEW MEXICO 87501	Revised 10-1
FILE		Sa. Indicate Type of Leuse
V.3.0.3.		
LAND DESICE		
OPERATOR .		5. State Oil & Gos Leosa No.
	_	B-1587
SUNDA		
	•	7. Unit Agreement Name
OIL CAS WELL	ormen- Water Injection Well	W. Pearl Queen Unit
Nome of Operator		B. Farm of Lease liame
0.15 0.11 0		1.
Gulf Oil Corporati	9. Weil No.	
• • • • • • • • • • • • • • • • • • • •		
P. O. Box 670, Hobbs, NM 88240		129
t. Location of reti		10. Field and Pool, or Widcal
N ·	660 FEET FROM THE South LINE AND 1980 FEET FRE	Pearl Oueen
UNIT LEVIL -	The state of the s	
Host	20 10C 35F	
THE WEST LINE, SECTI	IOH 29 TOWNSHIP 19S RANGE 35E NMP	
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
	3741' GL	Lea
16. Check	Appropriate Box To Indicate Nature of Notice, Report or C	ther Data
NOTICE OF I	NTENTION TO: SUBSEQUE	IT REPORT OF:
PERPORM PEMEZIAL WORK	PLUG AND ANANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABAHDON	COMMENCE DRILLING OPHS.	PEUG AND ABANDONMENT
肾.	CHANGE PLANS CASING TEST AND CEMENT JOB	
PULL OR ALTER TASING	Changed Tubing	v

17. Describe Prooned or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propagately SEE RULE 1103.

Lowered long string; pulled 30,000# on long string. Tubing parted at 2187'. Cut tubing at 4733', POH with tubing. Fished parted tubing. POH with tubing and packer. Put bull plug in wellhead. GIH with packer, 2-1/16" tubing, packer at 4732'. Clean location, hook up to injection line; resume injection. Complete after changing out injection tubing 6-7-81.