STATE OF NEW MEXICO THERGY AND MINERALS DEPARTMENT

· · · · · · · · · · · · · · · · · · ·		
88 87 COPIES ACCEIVES		
POITRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
SPERATOR	1	

OIL CONSERVATION DIVISION		
DISTRIBUTION P. O. BOX 2088	Form C-103	
SANTA FE, NEW MEXICO 87501	Revised 10-1-78	
FILE		
U.S.G.S.	5a. Indicate Type of Lease	
LAND OFFICE	State X Fee	
OPERATOR	5. State Cil & Gas Lease No.	
	E-1638	
SUNDRY NOTICES AND REPORTS ON WELLS (10 NOT USE THIS FORM FOR PROPOSALS TO CHICL OR TO GEFFER OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.)		
[V] CAB []	7. Unit Agreement Hame	
STHER.	West Pearl Queen Unit	
s e of Operator	8. Farm or Lease Name	
Gulf Oil Corporation		
Ediress of Operator	9. Well No.	
P. O. Box 670, Hobbs, NM 88240	133	
ocition of Well	10, Field and Pool, or Wildcat	
IT LETTER C . 660 FEET FROM THE NOTTH LINE AND 1980 FEET	Pearl Oueen	
1.1 West LINE, SECTION 31 TOWNSHIP 19 RANGE 35		
15. Elevation (Show whether DF, RT, GR, etc.)	12. County	
3729' GL		
	Lea \\\\\\\	
Check Appropriate Box To Indicate Nature of Notice, Report of	or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. CHANGE PLANS CASING TEST AND CEMENT JQB	ALTERING CASING Re- Plug and abandonment X	
OTHER		
OT (FR		

Drill cement to 2000'. Perf 330' with (4) ½" JHPF 90° . Break down perf at 3300%, no sign of circulation on 13-3/8" casing. Set cement retainer at 3232. Pump 100 sacks Class "C" cement at 2100# at $2\frac{1}{2}$ BPM. Perf 1900'-1901' with (4) $\frac{1}{2}$ " 90° phased holes. Set cement retainer at 1835'. Pump 100 sacks Class "C" cement at 3 BPM with 1200#. Pump 75 bbls abandonment mud 1900' to surface. Pump 25 sacks (60') plug of Class "C" cement from surface. Install dry hole marker, clean location. P&A complete 11-2-80.