

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-03264
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-1638
7. Lease Name or Unit Agreement Name West Pearl Queen Unit
8. Well No. 152
9. Pool name or Wildcat Pearl Queen
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3723' GL

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER TA-Injection
2. Name of Operator Pyramid Energy, Inc.
3. Address of Operator 10101 Reunion Place, Ste. 210 San Antonio, TX 78216
4. Well Location Unit Letter H : 1650 Feet From The North Line and 330 Feet From The East Line Section 31 Township 19S Range 35E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Temporarily Abandon Wellbore <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  
05/24/94 Ran in hole with tubing and tagged plug at 4665'. Spotted 25 sack cement plug on top of bridge plug. Circulated hole with mud laden fluid. Ran tubing and packer to test casing. Casing held 500 psi with no leak off. Pulled tubing and packer and packed off well. Pressured casing to 600 psi for 30 minutes to record pressure chart. Casing held. Bled pressure and rigged down. Well temporarily abandoned.

This Approval of Temporary  
Abandonment Expires 6-1-99

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Scott Graef TITLE Operations Manager DATE 06/01/94  
TYPE OR PRINT NAME Scott Graef TELEPHONE NO.

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE JUN 07 1994  
CONDITIONS OF APPROVAL, IF ANY:

