VERGY AND MINERALS DEPARTME			TION DIVISION		• Fora C-103
DISTRIBUTION	P. O. BOX 2088 SANTA FE, NEW MEXICO 87501			. Revised 10-1-71	
SANTA FE	SANI	A FE, NEW	MEXICO 87501	r	Sa. Indicate Type of Lease
U.S.O.S.				1	
LAND OFFICE				Ļ	
OPERATOR]				5, State Oll & Gas Lease No.
SLINDD	Y NOTICES AND R	EPORTS ON	WELLS		
the war was that forth for PRO	POSALS TO DRILL OR TO DI	C.101) FOR SUC	ICK IO V DIAAFMEMI MEREMAA	91 A .	
		-			7, Unit Agreement Name
•14. A set A					West Pearl Queen Unit
ame of Operator			<u></u>		8. Form or Lease Hame
Chevron U.S.A.	. Inc.		•		
ddress of Operator		<u></u>			9. Well No.
P.O. Box 670	Hobbs NM 8	8240		+-	## 150
	nobbs, nn o	0240			10. Field and Pool, or Wildcas
ocation of Well F 10	980	North	1980		Pearl Queen
UNIT LETTER	FEET FROM TH	¢	LINE AND	_ FEET FROM	
West	32	19S	35E		
THE LINE, SECTION		18HIP			
			00 07 00		12. County
15. Elevation (Show whether DF, RT, GR, etc.)					
	3719 <u>GL</u>		·		Lea ()))))))
Check	Appropriate Box To	o Indicate N	ature of Notice, Rep	ort or Oth	er Data
	TENTION TO:		SUE	SEQUENT	REPORT OF:
···· ··· ··· ··· ··· ··· ··· ··· ··· ·	PLUG AN	0 ABAHDON	REMEDIAL WORK		ALTERING CASING
PORM REMEDIAL WORK			COMMENCE DRILLING OPHS.		PLUG AND ABANDONMENT
APORARILY ABANDON	CHANGE		CASING TEST AND CEMENT		
L OR ALTER CASING			0THER		
Isolate and Repa	air Casing Leak	ا بك ا			
Describe Proposed or Completed Or	perations (Clearly state a	ill pertinent deta	ils, and give pertinent dat	es, including	estimated date of starting any propos
					•
work) SEE RULE 1103.					•

Drillout cement. TIH with tubing. Test casing and packer to 500 psi for 30 minutes. Return to injection. • .

-

18. 1 hereby certify that the information above is true and c	/	est of my knowledge and belief. Division Drilling Manager Date 2-7-1986
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT SUPERVISOR		FEB 1 1 1986
CONDITIONS OF APPROVAL, IF ANYI	•	

.



4 :