

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WE' PI NO. 0-025-03276
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-5886
7. Lease Name or Unit Agreement Name West Pearl Queen Unit
8. Well No. 149
9. Pool name or Wildcat Pearl Queen
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3720' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER TA - Oil Well
2. Name of Operator Pyramid Energy, Inc.
3. Address of Operator 10101 Reunion Place, Suite 210 San Antonio, TX 78216
4. Well Location Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line Section 32 Township 19S Range 35E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3720' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
OTHER: Locate casing leak and either TA <input checked="" type="checkbox"/> or P&A wellbore.	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On May 7, 1994 the captioned well failed a casing integrity test. To bring the wellbore into compliance, the following procedure will be performed:

- 1) Locate casing leak with tubing and packer.
- 2) Spot 5 sack cement plug on top of CIBP at 4740' and circulate hole with mud laden fluid.
- 3) Contact the NMOCD District Office and obtain instructions to TA the wellbore. If conditions exist that do not allow the wellbore to be TA, it shall be plugged and abandoned in accordance with NMOCD rules and regulations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Scott Graef TITLE Operations Manager DATE 05/18/94
TYPE OR PRINT NAME Scott Graef TELEPHONE NO. (210) 308-8000

(This space for State Use)

APPROVED BY _____ TITLE DISTRICT SUPERVISOR DATE _____
CONDITIONS OF APPROVAL, IF ANY:

ORIGINAL SIGNED BY JEFFY DEXTON
DISTRICT SUPERVISOR

RECEIVED

MAY 23 1994

**JOHN HUBBS
OFFICE**