	~	
		Form C+103 Supersectes ()td
		C-1 02 and C-103
NEW MEXICO	OIL CONSERVATION COMMISSION	Effective 1-1-65
		Sa. Indicute Type of Leano
		State X Fee
		5. State Off & Gan Leage No. E-1932
Y ROTICES AND REPO	ORTS ON WELLS	
IS FOR PLANT IN (POTHICH	101, FOR SHEAR PROPUSALS, 1	V. Unit Agreement Nor.e
TT-h T		
other Water in	jection well	West Pearl Queen Unit
		9, Well No.
-t 000/0		
10 88240		160 10. Field and Pool, or Wildeat
0.00	C	
FEET FROM THE	SOUTA LINE AND 1980 FEET	Pearl Queen
20	10 0 25 7	
JZ TOWNSHIF	P RANGE NI	мъм. Д////////////////////////////////////
1 35. Elevetion (5k)		12. County
	3706' GL	Lea
Ippropriate Box To In	3706' GL adicate Nature of Notice, Report or	\
Appropriate Box To In ITENTION TO:	ndicate Nature of Notice, Report or	\
	ndicate Nature of Notice, Report or SUBSEQU	Other Data
TENTION TO:	ndicate Nature of Notice, Report or SUBSEQU	Other Data ENT REPORT OF:
TENTION TO:	ANDON REMEDIAL WORK	Other Data ENT REPORT OF:
PLUG AND AD	ANDON REMEDIAL WORK	Other Data ENT REPORT OF:
PLUG AND AD	ANDON REMEDIAL WORK COMMENCE DRILLING OFHS. CASING TEST AND CEMENT JOB	Other Data ENT REPORT OF: ALTERING CASSING PLUG AND ABARDONMENT
	<u>Y NOTICES AND REP</u> отния- Water In cico 88240 <u>980</u> рест гасы тне _ <u>32</u> томизы	100 88240 .980 FEET FROM THE South 1980 FEET FROM THE 32 TOWNSHIP 19-S RANCE 35-E NI 15. Elevetion (Show whether DF, RT, GR, etc.) 15. Elevetion (Show whether DF, RT, GR, etc.) 15. Elevetion (Show whether DF, RT, GR, etc.)

5060' TD, 5045' PB.

Attempted to pull injection tubing for approximately three weeks. Unable to recover tubing below 2470'. Loaded hole with abandonment mud. Set CI BP at 2448'. Spotted 50 sack cement plug on top of BP at 2448' to 1902'. Perforated 5-1/2" casing at 1800' with 2, 1/2" jet holes. Set cement retainer at 1700' and squeezed perforations at 1800' with 375 sacks of Class C cement containing 2% Ca Cl2 and 5# salt per sack. Maximum pressure 1150#. Capped retainer with 100' cement plug to 1600'. Perforated 5-1/2" casing with 2, 1/2" jet holes at 250'. Set retainer at 200' and squeezed perforations at 250' and circulated cement to surface out side 5-1/2" casing. Spotted cement plug on top of retainer at 200' to surface. Installed dry hole marker and cleaned location. Complete P & A March 16, 1978.

18. Thereby certify that the information above is true and complete to the best of my knowledge and belief.

stenro 1-6-6-6-6-6-6-	Area Engineer	PATE March 16, 1978
PEROVED DY U- A Stationia	OIL & GAS INSPECTOR	DATE

CONDITIONS OF APPROVAL, IF ANYI