

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVIS
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

5a. Indicate Type of Lease
State ☒ For ☐
5. State Oil & Gas Lease No.
E-5841

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - II" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL ☐ GAS ☐ OTHER ☐
2. Name of Operator
Gulf Oil Corporation Chevron USA
3. Address of Operator
P.O. Box 670, Hobbs, NM 88240
4. Location of Well
UNIT LETTER **C** **660** FEET FROM THE **North** LINE AND **1980** FEET FROM
THE **West** LINE, SECTION **33** TOWNSHIP **19S** RANGE **35E** NMPM.

7. Unit Agreement Name
N. Pearl Queen Unit
8. Farm or Lease Name
Pearl Queen
9. Well No.
141
10. Field and Pool, or Wildcat
Pearl Queen
15. Elevation (Show whether DF, RT, GR, etc.)
3714' GL
12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH of thg. Attempts to enter csq unsuccessful. Circ hole w/ abandonment
md. Spot cmt plug 796'-470'. Spot surf plug @ 100'. Operations
witnessed by OGD representative. Install dry hole marker. Clean
& clear location. Well P+ A 7-26-83.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED RDPite TITLE AREA ENGINEER DATE 8-3-83

APPROVED BY R. H. H. H. TITLE OIL & GAS INSPECTOR DATE JUN 30 1987
CONDITIONS OF APPROVAL, IF ANY: