

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State ☒ Fee ☐

5. State Oil & Gas Lease No.  
E-5841

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name West Pearl Queen Unit
2. Name of Operator GULF OIL CORPORATION	8. Farm or Lease Name
3. Address of Operator P. O. Box 670, Hobbs, NM 88240	9. Well No. 145
4. Location of Well UNIT LETTER <u>G</u> - 1980 FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>33</u> TOWNSHIP <u>19S</u> RANGE <u>35E</u> NMPM.	10. Field and Pool, or Wildcat Pearl Queen
11. Elevation (Show whether DF, RT, GR, etc.) 3698' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Kill well if necessary with 8.6# GKF. POH with 2-3/8" tubing. Set CIBP on 2-3/8" work string at 4700'. Circulate abandonment mud; pressure test casing to 500#. Cap CIBP with 35' cement. Pull up and spot a 100' cement plug 2280'-2380'. Pull up and spot another 100' cement plug 1880'-1980'. Reverse out excess cement if necessary. POH with 2-3/8" work string. Set a 50' surface cement plug. Place a dry hole marker on the well; clean and clean location as required.

THE COMMISSION MUST BE NOTIFIED 24 HOURS BEFORE THE DATE OF THE PROPOSED OPERATIONS FOR THE C-103 TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Beyn Stone TITLE Area Engineer DATE 7-11-80

APPROVED BY Jerry Sertoni TITLE Area Engineer DATE 7-11-80  
CONDITIONS OF APPROVAL, IF ANY: