## N.M. OIL CONS. CO. KISSION

	UNITED STATES P.O. BOX 1980 ARTMENT OF THE INTERIOR AU OF LAND MANAGEMENT	FORM APPROVED  S 24 Obudget Bureau No. 1004-0135  Expires: Murch 31, 1993  5. Lesse Designation and Sectial No.
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals		NMLC065649 6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of Well  Oil  Well  Well  Other  2. Name of Operator	8. Well Name and No. South Pearl Oueen Unit #24	
Xeric Oil & Gas Company 3. Address and Telephone No.		9. API Well No. 300250334300
P.O.Box 51311, Midland, Texas 79710 915/683-3171  4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		10. Field and Pool, or Exploratory Area
SWNE Section 9, T-2 330 FNL & 1980 FWL		Pearl Queen 11. County or Parish, State Lea County, N.M.
12. CHECK APPROPRIAT	TE BOX(s) TO INDICATE NATURE OF NOTICE, F	REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF A	CTION
Notice of Intent  Subsequent Report	Abandonment  Recompletion  Plugging Back  Casing Repair	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off
Final Abandonment Notice	Altering Casing  Other T/A  Clearly state all pertinent details, and give pertinent dates, including estimated date	Conversion to Injection  Dispose Water (Nee: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
Xeric requests peabandoned status injection wells a mation interval back to	ermission to carry this well in This well is surrounded by thrand has re-entry potential in the between 4896'-4910'. Xeric would a producing well after we have earl Queen Unit well #8,#9 and #	a temporarily ee (3) water ee Queen For- like to put
Signed Signed	Tric President	Date 10/17/94
(This space for (ORIG. Sun GD.)) J. Approved by Conditions of approval, if any: See	Tide PERMIT	MEER De 11/22/94 med within 96 days.

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any failer, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

P.02

## BUREAU OF LAND MANAGEMENT CARLSBAD RESOURCE AREA

## Temporary Abandonment of Wells on Federal Lands

## Conditions of Approval

According to 43 CFR 3162.3-4-c, "No well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer".

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- 1. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County call (505) 887-6544; for wells in Lea County call (505) 393-3612.
- A bridge plug or packer shall be set at a maximum of 50 feet above any open perforations or open hole.
- 3. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- 4. The production casing shall be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leak-off.

Wells that successfully pass the casing integrity test will be approved for Temporary Abandonment (TA) status for 12 months provided that the operator:

- 1. Submits a subsequent Sundry Notice requesting TA approval,
- 2. Attaches a clear copy or the original of the pressure test chart,
- 3. And attaches a detailed justification why the well should not be plugged and abandoned.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.