

STRAIGHT HOLE SURVEY RESULTS

TOTCO SURVEY

300'	$3/4^{\circ}$
600'	$1/2^{\circ}$
1200'	$3/4^{\circ}$
1650'	$3/4^{\circ}$
1850'	$3/8^{\circ}$
2300'	1°
2800'	2°
3300'	$3 \ 1/4^{\circ}$
3489'	3°
3680'	$2 \ 1/4^{\circ}$
3840'	1°
4025'	$1/2^{\circ}$
4170'	$1/2^{\circ}$
4660'	1°
4860'	$1 \ 3/4^{\circ}$
5050'	$1 \ 1/4^{\circ}$

DST 3698-3902

Tool open 1 hour, leak for 18 minutes and died; recovered 150 drilling mud IFP 110° FVP 110° 15 SIF 110°.