

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. **30-025-04029**

5. Indicate Type of Lease  
STATE ☐ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

**Northwest Eumont Unit**

8. Well No. **#124**

9. Pool name or Wildcat  
**Eumont Yates**

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator **Rhombus Operating Co., Ltd.**

3. Address of Operator  
**200 N. Loraine, Suite 1270, Midland, Texas 79711**

4. Well Location

Unit Letter **H** : **1,988** feet from the **North** line and **662** feet from the **East** line

Section **22** Township **19-S** Range **36-E** NMPM County **Lea**

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

**07/29/02** MIRU Triple N rig #25. POOH w/ rods. NU BOP. POOH w/ tbg and rods. RIH w/ gauge ring on wireline to 4,000'. POOH. RIH w/ 4½" HM tbg-set CIBP and set @ 4,014'. Circulated hole w/ mud and pumped 25 sx C cmt 4,014 - 3,634'. SDFN.

**07/30/02** Notified OCD, Buddy Hill. Pumped 25 sx C cmt 2,822 - 2,442'. Cut and pulled 1,563' 4½" csg. tally 1,570.33'. RIH w/ tbg and pumped 50 sx C cmt 1,600 - 1,371'. WOC and tagged @ 1,558'. Pumped 50 sx C cmt @ 1,558'. SDFN.

**07/31/02** Buddy Hill w/ OCD on location. Tagged cmt @ 1,411'. Pumped 30 sx C cmt 407 - 296'. Pumped 10 sx C cmt 60' to surface. RDMO.

**08/09/02** Cut off wellhead and capped well, covered pit and cellar, removed anchors.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE **Engineer** DATE **08/09/02**

Type or print name **James F. Newman, P.E.** Triple N Services, Inc. Telephone No. **915-687-1994**


(This space for State use)

Approved as to plugging of the Well Bore.

Liability under bond is retained until

surface restoration is completed.

DATE

APPROVED BY:   
Conditions of approval, if any:

GARY W. WINK  
OC FIELD REPRESENTATIVE II/STAFF MANAGER

**JAN 30 2003**