

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
B-3464

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR NOTICES TO OIL & GAS PRODUCERS OR TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT TO PRODUCE OIL & GAS FOR SUCH PURPOSES.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
TEXACO Inc.	NM 'F' State
3. Address of Operator	9. Well No.
P. O. Box 728, Hobbs, New Mexico 88240	1
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER I 3300 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 24 TOWNSHIP 19-S RANGE 36-E N.M.P.M.	Eunice Monument Grayburg San Andres
11. Elevation (Show whether DF, RT, CR, etc.)	12. County
3720' (DF)	Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up. Pull rods & pump. Install BOP. Log Well.
2. Perforate open-hole section w/2 JSPF @ 3899', 3903', 11', 14', 25', 29', 33', 39', 44', 47', 52', 62', & 3963'.
3. Set Packer @ 3805'. Acidize open-hole 3883' - 3999' w/4500 gal. 15% HE Acid, 500 gal. Mark II & 1400# rock salt.
4. Install pumping equipment. Test & return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Asst. Dist. Supt. DATE 9-9-77

APPROVED BY [Signature] TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: