Submit 3 copies to Appropriate District Office

State of New Mexico

Form C-103

, Minerals and Natural Resources Departm Revised 1-1-89 DISTRICT I OIL CONSERVATION DIVISION WELL API NO. P.O. Box 1980, Hobbs, NM 88241 2040 Pacheco St. 30-025-04053 **DISTRICT II** Santa Fe, NM 87505 5. Indicate Type of Lease P.O. Box Drawer DD, Artesia, NM 88210 STATE V FEE . DISTRICT III State Oil / Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 B-1431-3 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) North Monument B/SA Unit Blk. 9 OIL GAS 1. Type of Well V WELL WELL OTHER 2. Name of Operator 8. Well No. 14 **Amerada Hess Corporation** 3. Address of Operator 9, Pool Name or Wildcat P.O. Box 840, Seminole, TX 79360 **Eunice Monument G/SA** 4. Well Location **Unit Letter** Feet From The South Line and 1980 Feet From The West Line Section 25 Township _ 019N Range __036W **NMPM** LEA COUNTY 10. Elevation (Show whether DF, RKB, RT,GR, etc.) Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK **PLUG AND ABANDON** REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPERATIONS | PLUG AND ABANDONMENT **PULL OR ALTER CASING CASING TEST AND CEMENT JOB** OTHER: Convert to injection Well. OTHER: 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Ref: Administrative Order No. WFX-765

Plan to MIRU pulling unit, install BOP & TOH w/prod. eqpt. TIH w/5-7/8" bit to TD at 3939' & TOH. TIH w/RBP set at 3760'. Dump sand on top plug & perform csg. int. test. Shoot squeeze holes at 2450' & attempt to est circ. between 6-5/8" & 8-5/8" csg. Run Dye Caliper to determine cement volume. Cement squeeze. WOC. Drill out cement & press. test to 700 PSI. TOH w/RBP. Acidize O.H. fr. 3939' - 3808' w/2000 gal. HCL acid. Swab well. TIH w/inj. pkr. and tbg. Begin injection operations.

Thereby certify that the information about its true and complete to the best of my knowledge and belief. SIGNATURE TITLE Bus. Svc. Spec. II TYPE OR PRINT NAME Roy L. Wheeler Ir	DATE 11/15/2000
TYPE OR PRINT NAME Roy L. Wheeler, Jr.	TELEPHONE NO. 915-758-6778
CONDITIONS OF APPROVAL, IF ANY: DESCRIPTIONS	in the second
	DATE