STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON TITLE

CONDITIONS OF APPRISTRUCT SUPERVISOR

NO. OF COPIES ACCEIVES	OIL CONSERVA	TION DIVISION	Form C-103	
DISTRIBUTION			Revised 10-1-7	
SANTA FE	SANTA FE, NEW MEXICO 87501			
FILE	4		5a. Indicate Type of Lease	
U.S.G.S.	1		State X Fee	
OPERATOR .	-		5. State Oil & Gas Lease No.	
O'ERATON	J		B1431	
	W WOTIEFS AND DEPORTS ON	WELLE		
SUNDA	RY NOTICES AND REPORTS ON OPERS TO DRILL OR TO DEEPEN OF PLUG B	ACK TO A DIFFERENT RESERVOIR.		
	TION FOR PERMIT -** (FORM C-101) FOR SUC	H PROPOSALS.)	7. Unit Agreement Name	
1. OIL T3 6A8 T			7. 0	
WELL X WELL	OTHER-			
2. Name of Operator	viame of Operator		8. Farm or Lease Name	
Amorada Hose Comorati	Amerada Hess Corporation		State "T"	
3. Address of Operator	Atterded ness corporation Address of Operator		9. Well No.	
		1		
Drawer D. Monument, New Mexico 88265		10. Field and Pool, or Wildcat		
			Eunice Monument G/SA	
UNIT LETTER	UNIT LETTER N , 660 FEET FROM THE SOUTH LINE AND 1980 FEET FRO			
THE West LINE, SECTI	10H 25 TOWNSHIP 19S	range36E hmp	~ (
			-1111111111111111111111111111111111111	
	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County	
	3628' DF		Lea \\\\\\\	
ib. Check	Appropriate Box To Indicate N	lature of Notice. Report of C	ther Data	
	NTENTION TO:		NT REPORT OF:	
NOTICE OF I	NIENTION TO:	33332432	.,=. •	
\Box		্ ত		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT	
PULL OR ALTER CABING	CHANGE PLANS	CASING TEST AND CEMENT JOB	_	
		OTHER		
OTHER				
		l di a di a casi da		
 17. Describe Proposed or Completed O work) SEE RULE 1603. 	perations (Clearly state all pertinent deta	ails, and give pertinent dates, includi	ng estimated date of starting any propose	
· · · · · · · · · · · · · · · · · · ·	February 17, 1984 - Pul	lod mode name to the	Pan $A=3/A$ " bit on $2=7/8$ "	
replicaty 13, 1964 to 1	fill in one hole of 202	Ol Coloctively porfer	ated C/SA zono in coop	
tbg. & checked top of fill in open hole at 3929'. Selectively perforated G/SA zone in open hole fr. 3825' to 3928'. Ran pkr. & tbg. & set pkr. at 3760'. Acidized G/SA zone in open				
hole fr. 3825' to 3928	b. Ran pkr. & tog. & se	t pkr. at 3/60°. Acidi	zed G/SA zone in open	
hole fr. 3808' to 3939	9' w/2500 gal. 15% NE aci	d using rock sait as di	verter. Swapped 10ad.	
Re-ran tbg., pump & ro	ods and resumed production	n.		
		•		
		•		
	•			
	•		·	
•				
			•	
18. I hereby certify that the information	n above is true and complete to the best	of my knowledge and belief.		
. /				
0 2 2 1 / .			2.37.04	
BIGHED CO TIME	4 TITLE _S	upv. Adm. Ser.	DATE	
			FFR 20 1984	

FEB 20 1984
HODES SHICE