

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

FEB 20 1970
Form C-102
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>5a. Indicate Type of Lease State XX Fee <input type="checkbox"/></p> <p>5. State Oil & Gas Lease No. NM-2056</p>
<p>1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/></p> <p>2. Name of Operator Gulf Oil Corporation</p> <p>3. Address of Operator Box 670, Hobbs, New Mexico 88240</p> <p>4. Location of Well UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 25 TOWNSHIP 19-S RANGE 36-E NMPM.</p>	<p>7. Unit Agreement Name</p> <p>8. Farm or Lease Name Graham State (NCT-C)</p> <p>9. Well No. 7</p> <p>10. Field and Pool, or Wildcat Monument</p>	<p>11. Elevation (Show whether DF, RT, GR, etc.) 3651' GL</p> <p>12. County Lee</p>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
<p>PERFORM REMEDIAL WORK <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	<p>PLUG AND ABANDON <input type="checkbox"/></p> <p>CHANGE PLANS <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3975' TD.

Pulled rods, pump and tubing. Ran packer and tubing. Set packer at 3752'. Treated open hole interval 3835' to 3975' with 1000 gallons of 28% NE acid. Flushed with 40 barrels of brine water. Maximum pressure 2000#, minimum 0#. AIR 4.1 bpm. ISIP 300#, after 1/2 minute on vacuum. Pulled tubing and packer. Ran tubing and set at 3963'. Swabbed and cleaned up. Ran rods and pump and returned well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

<p>ORIGINAL SIGNED BY SIGNED C. D. BORLAND</p>	<p>TITLE Area Production Manager</p>	<p>DATE February 20, 1970</p>
<p>APPROVED BY [Signature]</p>	<p>TITLE SUPERVISOR DISTRICT 1</p>	<p>DATE [Signature]</p>

CONDITIONS OF APPROVAL, IF ANY: