State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Revised 1-1-89

P.O. Box 1980, Hobbs, NM 88240 310		ONSERVATION DIVISION 10 Old Santa Fe Trail, Room 206 Santa Fe, New Mexico 87503	WELL API NO.
			30-025-04083
P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lasse STATE FEE X
DISTRICT III 1000 Rio Brizos Rd., Aziec, NM 87410			6. State Oil & Gas Lonse No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			<i>`````````````````````````````</i>
			7. Loane Name or Unit Agreement Name
DIFFERENT RESE	RVOIR. USE ' 2-1011 FOR SI	"APPLICATION FOR PERMIT" JCH PROPOSALS.)	Amos Persons Lease
1. Type of Well:			
OIL X WELL		OTHER	
2. Name of Operator			8 Well No.
Trio Oil Company			9. Pool name or Wildon
3. Address of Operator P.O. Box 10.76	unica N	ewMexico 88231	Eumont Y-SR-ON
4. Well Location	direc, N	ewiexico odzai	Editoric 1-5K-ON
Unit Letter _ I : _ 19	80 Peet Fro	m The South Line and 6	60 Foot From The East Line
27		100	
Section	Townshi	p 19S Range 36E O. Elevation (Show whather DF, RKB, RT, GR, etc.)	NMPM Lea County
		C Devador (Saba Maria) Di (100), III, ON, III)	
11. Check	Appropria	te Box to Indicate Nature of Notice,	Report, or Other Data
NOTICE OF IN	TENTION	ITO: SI	JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG	AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHAN	GE PLANS COMMENCE DRILL	ING OPNS. PLUG AND ABANDONMENT X
PULL OR ALTER CASING		CASING TEST AND	CEMENT JOB
OTHER:		OTHER:	_
12. Describe Proposed or Completed Oper work) SEE RULE 1103.	rations (Clearly	state all pertinent details, and give pertinent dates,	including estimated date of starting any proposed
P & A as follows:	2-6-95	MIRU put on BOP, run 2-3/8"	tbg., screw on to 2-3/8" tbg.
	• •	@ 199', Circ, mud (251# sal	t gel per Bbl.) free pt. 2-3/8"
and the same of the same			"C" cmt. down tbg. to 3200'. Shut
		well in, shut down.	
	2-7-95	Tag cmt. in 2-3/8" thg. @ 3	020' 50sxs, plg. from 3020'-3700'
	2 , ,,		Cut 2-3/8" tbg. @ 600', spot 25sxs
		from 600' up. Wait to tag	cmt. @ 360'. Plg. from 600'-360'.
		Put tbg. to 250', circ. 25s	xs to surface. Shut down.
•	2_8_05	Cut off wollhood install d	ry hole marker & cleaned loc.
	2-0-75	ode off wellhead, install d	ry note market a creamed foc.
I hereby certify that the information above is tru	e and complete to	the best of my knowledge and balicf.	
alet V	1 5	Prod. Fore	eman <u>2-20-95</u>
Charles N.	France	III	TELEPHONE NO (505) 394-2506
TYPE OR PRINT NAMP	Evalls		
(This space for State Use)			ا JAN 3 0 2003 رد
		Approved as to plugging of the	Well Bore.
ATTOMET BY		Liability und me ad is retained	()*'
CONDITIONS OF ACT TO YALL & ANY	•	surface restoration is completed	L NOW
OC FIELD REPRESENTATIV	E#I/STAFF	MANAGER	2. p.
.*			