

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

NEW MEXICO OIL CONSERVATION COMMISSION

5a. Indicate Type of Lease
State ☐ ☒ ☐
5. State Oil & Gas Lease No.

SUMMARY NOTICE OF INTENTION TO DRILL OR PLUG BACK OR PLUG BACK TO A DIFFERENT RESERVOIR.
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR PLUG BACK OR PLUG BACK TO A DIFFERENT RESERVOIR.
SEE APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)

1. Name of Operator Amerada Hess Corporation	7. Unit Agreement Name
2. Address of Operator Drawer "D", Monument, New Mexico 88265	8. Farm or Lease Name W.A. Weir
3. Location of Well UNIT LETTER <u>L</u> <u>660</u> FEET FROM THE <u>West</u> LINE AND <u>1960</u> FEET FROM THE <u>South</u> LINE, SECTION <u>35</u> TOWNSHIP <u>19-S</u> RANGE <u>36-E</u> NMPV.	9. Well No. <u>1</u> <u>3</u>
10. Field and Pool, or Willam Dunbar-Monument (G-SA)	11. Elevation (Show whether DF, RT, GR, etc.)
12. County Loc	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	
		OTHER ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan To: Set Cast iron bridge plug above G-SA oil section. Log and perforate upper G-SA as per logs. Acidize with 15% NE acid and swab test. Run production equipment and complete in G-SA gas section.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. B. Black TITLE Supvr., Admin. Services DATE 5-5-75
APPROVED BY W. B. Black TITLE Supvr., Admin. Services DATE 5-5-75
CONDITIONS OF APPROVAL, IF ANY: