

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-04121

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Amerada Hess Corporation

8. Well No.

03

3. Address of Operator

Drawer D, Monument, New Mexico 88265

9. Pool name or Wildcat

Eunice Monument G/SA

4. Well Location

Unit Letter C : 660 Feet From The North Line and 1980 Feet From The West Line

Section 35 Township 19S Range 36E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: Cement squeeze. ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to MIRU pulling unit. Remove wellhead, install BOP & TOH w/tbg. Dump 50' sand on top RBP. Run cement bond log fr. RBP to surface. Perf. csg. w/4 shots above cement top. TIH w/ pkr. & est. circ. into perfs. & TOH. TIH w/6-5/8" cement retainer set above perf. holes & test tbg. to 2500#. Circ. cement using light cement tailed w/Class "C" neat. WOC. TIH w/5-7/8" bit & drill out cement, retainer & cement. Test squeeze holes to 500# & obtain chart. TOH w/bit. Remove BOP & wellhead & replace w/new wellhead. Install BOP, TIH w/retrieving head, latch onto RBP & TOH. TIH w/tbg. Remove BOP, install well head, & TIH w/pump & rods. RDPU, clean location & resume prod. well.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

R. L. Wheeler, Jr.

TITLE

Supv. Adm. SVC.

DATE 8-24-92

TYPE OR PRINT NAME

R. L. Wheeler, Jr.

TELEPHONE NO. 393-2144

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT I SUPERVISOR

AUG 27 '92

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: