Submit 3 Copies to Appropriate District Office

CONDITIONS OF APPROVAL, IF ANY:

For any, Minerals and Natural Resources Departments

Forte C	-103
Revised	1-1-59

DISTRICT 1 P.O. Box 1980, Hobbs, NM 8824)	OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088		WELL API NO.				
DISTRICT II			3002504126				
P.O. Drawer DD, Artesia, NM 88210	5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		5. Indicate Type of Lease				
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No				
			a State Oil & Gas Lease No	.			
SUNDRY NOTI	CES AND REPORTS ON WEL	LS					
DIFFERENT RESER	PPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A RVOIR. USE "APPLICATION FOR PERMIT" 101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agre	ement Name			
1. Type of Well:			NORTH MONUMENT	G/SA UNIT			
2. Name of Operator	on ex		BLK. 13				
AMERADA HESS CORPORAT	ION		& Well No.				
3. Address of Operator			9. Pool name or Wildcat				
POST OFFICE DRAWER D, 4. Well Location	MONUMENT, NEW MEXICO	88265	EUNICE MONUMENT	G/SA			
	COUTU						
Unit Letter 0 : 660	Feet From The SOUTH	Line and198	Feet From The	EAST Line			
Section 35	Township 195 Ra	nge 36E	NMPM LEA				
	10. Elevation (Show whether		NMPM LEA	County			
	(////)						
II. Check	Appropriate Box to Indicate 1	Nature of Notice, R	eport, or Other Data				
NOTICE OF INT	ENTION TO:		SEQUENT REPOR	T OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK					
TEMPORARILY ABANDON				ig casing			
\	CHANGE PLANS	COMMENCE DRILLING	OPNS. L PLUG AN	ND ABANDONMENT			
PULL OR ALTER CASING X		CASING TEST AND CE	MENT JOB				
OTHER: Replace O	Sq. X	OTHER:					
12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. NMGSAU #1315 Plan 70 Move in and rig up pulling unit. (Casing Integrity test was performed and leaks were found from 231' to 262'.) Plans are to back-off and replace approximately 300' of 7" casing. Perform casing integrity test, and upon passing return well to production. Rig down and move out pulling unit. Clean and clear location.							
			a -compage				
I hereby certify that the information above is true	and complete to the best of my knowledge and	belief.					
SIGNATURE Leve	y L Harry m		ccictant	02-01-94			
/ X	T. J. June III	B Sia Stall A	DATE DATE	02-01-34			
TYPE OR FRINT NAME	Terry L. Harvey	•, .	TELEP	HONE NO. 393-2144			
(This space for State Use) ORIGINAL SIGN DISTRICT	ED BY JERRY SEXTON I SUPERVISOR			FE2 00 1084			
APPROVED BY	m	u2	DATE	- lwist			

HEGEIVED

FEB (* 8 1994

OCD HOBBS OFFICE