SOUTHEAST NEW MEXICO PACKER LEAKAGE TEST

		Oil Company		Lease	Stat	A-1'A"		ell o. 1
Location of Well	n Unit	Sec 35	Twp	198	Rge	368	County	Jee.
	Name of Res	ervoir or Pool	Type of (Oil or	Prod M	ethod of Prod	Prod.	Medium	Choke Si
Upper Compl	Descrit	<u> </u>	Coll of		low, Art Lift		r Csg)	
Lower	Momment		Oi		Flow			20/664
Ochpi						- Zui	ing	12/64"
Doth		. /1		TEST NO				
		t (hour, date)		6-18-6			Upper	Lower
		, date):		i , 6- 19 - 6			mpletion	Complet
		e zone produci		+				
		g of test						445
Stabilize	ed? (Yes or N	No)	••••••	• • • • • • •	• • • • • • • • • • • • • •	•••••	yes	no
Maximum)	pressure duri	ing test	• • • • • • • • • • •	• • • • • • • •	• • • • • • • • • • • • • • • • • • • •		775	549
Minimum p	pressure duri	ing test	• • • • • • • • • • • • •	• • • • • • •	•••••••	••••	559	445
Pressure	at conclusion	on of test	• • • • • • • • • • •	• • • • • • •	•••••••	•••••	559	549
Pressure	change durin	ng test (Maximu	um minus Min	imum)	••••••		216	104
Was press	sure change a	n increase or	a decrease?		••••••	••••	Decrease	Increas
Oil Produ	u c tion	date): 9:0		Product	Producti	.on	24 1	cours
During Te	est:	bbls; Grav	Dur	ing Test	1010	MCF;	GOR	•
Remarks_	ned at (hour,	date):	FLOW T	ring Test	2	U Con	opper	Completi
Remarks Well open	ned at (hour,	date):	FLOW T	ring Test EST NO.	2	U Con	pper pletion	Completi
Remarks	ned at (hour, by (X) th at beginning	date):he zone produc of test	FLOW T 9:00 AN, (ring Test	2	Con	opper spletion	Completi
Well open Indicate Pressure	ned at (hour, by (X) th at beginning	date):he zone produc of test	FLOW T	ring Test	2	Con	opper upletion 762 no	Completi
Well open Indicate Pressure Stabilize	ned at (hour, by (X) that beginning d? (Yes or No ressure during	date):he zone produc of test	FLOW T	ring Test	2	Con	opper upletion 762 no 766	Completi
Remarks	ned at (hour, by (X) th at beginning d? (Yes or No ressure during ressure during	date):he zone produc of test b) ng test	FLOW T	ring Test	2	Con	pper pletion 762 no 766 762	Completic X 582 yes
Remarks	ned at (hour, by (X) th at beginning d? (Yes or No ressure durin ressure durin at conclusion	date):he zone produc of test b) ng test n of test	FLOW T	ring Test	2	Con	762 no 766 766	Completi X 582 yes 582
Remarks	ned at (hour, by (X) th at beginning d? (Yes or No ressure durin ressure durin at conclusion	date):he zone produc of test b) ng test	FLOW T	ring Test	2	Con	762 no 766 766	X 582 yes 582 582 52
Remarks	ned at (hour, by (X) that beginning d? (Yes or No ressure during at conclusion change during ure change and ed at (hour,	date):he zone product of test	FLOW T 9:00 AN, (ing. m minus Minima decrease?. M, 6-22-62	ring Test	Total time Production	Com	pper pletion 762 no 766 762 766 h	Completi X 582 yes 582 582 582 582 582 582 582 582 582 582
Well open Indicate Pressure Stabilize Maximum pr Fressure of Pressure of Mas pressure Tell close	ned at (hour, by (X) th at beginning d? (Yes or No ressure durin ressure durin at conclusion change during ure change an ed at (hour, ction st: 80 b	date):he zone product of test	FLOW T 9:00 AM, ing. m minus Minima decrease?. M, 6-22-62 Gas I API ; Durin	ring Test EST NO. 6-21-62 Productions Test_	Total time Production 91.1	Com	pper pletion 762 no 766 762 766 h	Completi X 582 yes 582 582 582 590 Decrease
Remarks	ned at (hour, by (X) the at beginning d? (Yes or No ressure during ressure during at conclusion change during ure change an ed at (hour, ction st: 80 b	date):he zone product of test	FLOW TO 9:00 AN, on minus Mining decrease?. M, 6-22-62 API ; During the control of the control	TEST NO. -21-62 num) Production Test_ tained i	Total time Production 91.1	Com Com MCF; GOF	pper pletion 762 766 766 4 Increase 24 b	Sompleti X 582 yes 582 582 582 582 582 582 582 583 Sours 139
Remarks	ned at (hour, by (X) that beginning d? (Yes or No ressure during at conclusion change during the change and at (hour, ction st: 80 b	date):he zone product of test	FLOW TO 9:00 AN, ing	TEST NO. -21-62 num) Production Test_ tained i	Total time Production 91.1	Com Com MCF; GOF	pper pletion 762 766 766 4 Increase 24 b	Sompleti X 582 yes 582 582 582 582 582 582 582 583 Sours 139

July 3, 1962

SOUTHEAST NEW MEXICO PACKER LEAKAGE TEST INSTRUCTIONS

1

- 1. A packer leakage test shall be commenced on each multiply completed well within seven days after actual completion of the well, and annually thereafter as prescribed by the order authorizing the multiple completion. Such tests shall also be commenced on all multiple completions within seven days following recompletion and/or chemical or fracture treatment, and whenever remedial work has been done on a well during which the packer or the tubing have been disturbed. Tests shall also be taken at any time that communication is suspected or when requested by the Commission.
- 2. At least 72 hours prior to the commencement of any packer leakage test, the operator shall notify the Commission in writing of the exact time the test is to be commenced. Offset operators shall also be so notified.
- 3. The packer leakage test shall commence when both zones of the dual completion are shut-in for pressure stabilization. Both zones shall remain shut-in until the well-head pressure in each has stabilized and for a minimum of two hours thereafter, provided however, that they need not remain shut-in more than 24 hours.
- 4. For Flow Test No. 1, one zone of the dual completion shall be produced at the normal rate of production while the other zone remains shut-in. Such test shall be continued until the flowing wellhead pressure has become stabilized and for a minimum of two hours thereafter, provided however, that the flow test need not continue for more than 24 hours.

- Following completion of Plow Test No. 1, the well shall again be shutth, in secondance with Puragraph 3 above.
- 5. Figh Test Re 2 man, be conducted even though no leak was indicated during Filey Rest Ro. 1. Procedure for Flow Test No. 2 is to be the same as for Flow Test Re., sencept that the previously produced zone shall remain wherein while the previously shut-in zone is produced.
- 7 All pressures imbughout the entire test, shall be continuously whosuled and recorded with rangeding pressure gauges, the accuracy of which must be checked with a deadweight tester at least twice, once at the beginning and once at the rad, of each flow test.

In the second of the last confidence of the less shall be filed in triplicate this is days after completen of the test. Tests shall be filed with the appropriate first recompleten of the New Mexico Oil Conservation Comparison on Southers New Mexico Packer Leakage Test Form Revised 11-1-58, together with the original pressure recording gauge charts with all the deadweight pressures which were taken indicated thereon. In lieu of filling the aforesaid charts, the operator may construct a pressure versus time curve for each zone of each test, indicating thereon all pressure changes which way be reflected by the gauge charts as well as all deadweight pressure readings which were taken. If the pressure curve is submitted, the original chart must be permanently filed in the operator's office. Form Collé shall also accompany the Packer Leakage Test Form when the test period coicilies sith a gas-oil ratio test period.

ge» (# # # 1
96 :	
330	