

COPIES RECEIVED	
DISTRIBUTION	
DATE	
FILE	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
Lease ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REPER OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - FORM C-101 FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Amerada Hess Corporation	8. Farm or Lease Name J.P. Phillips
3. Address of Operator Drawer "D", Monument, New Mexico 88265	9. Well No. 1
4. Location of Well UNIT LETTER A 330 FEET FROM THE North LINE AND 330 FEET FROM East LINE, SECTION 1 TOWNSHIP 20-S RANGE 36-E NMPM.	10. Field and Pool, or Wildcat Sunice-Monument (C-3A)
15. Elevation (Show whether DF, RT, GR, etc.) 3586' DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	Temp. Abandon <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pulled tubing. Set cast iron bridge plug at 3650' with 10' cement on top. Perforated 7" casing w/3 shots at the following depths: 3579', 3581', 3583', 3585', 3587', 3589', 3604', 3606', 3608', 3617', 3620', 3622', 3625', 3628', 3630' and 3632'. Total 48 holes. Acidized perfs. with 2500 gals. 15% NE acid. Swab tested. Set Cast Iron bridge plug at 3570' with 2 sx. cement on top. Top of cement at 3559'. Perforated casing with 3 shots at 3481', 3483', 3485', 3490', 3501', 3503', 3523', 3533', 3539', 3536'. Acidized perfs. 3481' to 3556' with 2000 gals. 15% NE acid. Swab tested. Perforated casing from 3506' to 3518', 3521' to 3525', 3530' to 3534' with one shot per foot. Total 23 holes. Acidized perfs. 3481' to 3556' with 3000 gals. 15% NE acid. Swab tested. Non-commercial.

Closed all valves & T.A.

Ed Jones 10/1/75

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *[Signature]* TITLE Supver., Admin. Services DATE 6-24-75

APPROVED BY _____ TITLE _____ DATE 10/1/75

CONDITIONS OF APPROVAL, IF ANY