

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Amerada Hess Corporation		8. Farm or Lease Name J. R. Phillips
3. Address of Operator Drawer D, Monument, New Mexico 88265		9. Well No. 4
4. Location of Well UNIT LETTER B 1980 FEET FROM THE East LINE AND 660 FEET FROM THE North LINE, SECTION 1 TOWNSHIP 20-S RANGE 36-E N.M.P.M.		10. Field and Pool, or Wildcat Eunice Monument G/SA
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to pull rods & pump, & check for fill and clean out if necessary. Drill cement plug inside 5-1/2" csg. to 3730', run pkr. & tbq. & test cement plug at 3730'. Using pkr, check for water entry. Drill out cement to 3770', perf. 5-1/2" csg. at 3760' w/four shots, set retainer at 3725' & pump 200# gel down annulus & squeeze thru 5-1/2" csg. perf. fr. 3652' to 3708' w/gel breaker set for two days. Squeeze off water flow thru 5-1/2" csg. perf. at 3760' w/max. 500# press. Reverse out. Swab test prod. perfs. fr. 3652' to 3708', re-run tbq., pump & rods and resume production.

THE COMMISSION MUST BE NOTICED
24 HOURS PRIOR TO COMMENCING WORK

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED E. B. Fisher TITLE Supv. Adm. Ser. DATE 3-9-81

APPROVED BY TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: