

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-04156
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-1656-2
7. Lease Name or Unit Agreement Name NORTH MONUMENT G/SA UNIT BLK. 18	
8. Well No.	15
9. Pool name or Wildcat	EUNICE MONUMENT G/SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> INJECTION WELL	2. Name of Operator Amerada Hess Corporation
3. Address of Operator P.O. DRAWER D, MONUMENT, NM 88265	4. Well Location Unit Letter <u>0</u> : <u>660</u> Feet From The <u>SOUTH</u> Line and <u>1980</u> Feet From The <u>EAST</u> Line Section <u>2</u> Township <u>20S</u> Range <u>36E</u> NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: CONVERT TO INJECTION WELL. ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #1815 (01-21-97 THRU 01-28-97)

TYLER WELL SVC. RU. PULLED & LAID DWN. PROD. EQUIP. INSTALLED BOP & RELEASED TAC. TOH W/TBG. RAN A RBP ON 118 JTS. OF TBG. SET THE RBP @ 3,747'. STAR TOOL LOADED THE CSG. & ATTEMPTED TO CIRC. W/200 BBLs. FW. THE RBP LEAKED. LATCHED ONTO & RELEASED THE RBP. RESET THE PLUG @ 3,725'. LOADED THE CSG. W/40 BBLs. FW & CIRC. CLEAN W/80 BBLs. FW. TST'D. THE 7" CSG. TO 540# FOR 30 MINS. OK. RELEASED THE RBP & TOH W/TBG. & PLUG. RAN A BIT. TAGGED BTM. @ 3,914' FOR 7' OF FILL. BROKE CIRC. & CLEANED OUT FILL TO TD @ 3,921' W/320 BBLs. FW. TOH W/TBG. & BIT. ROTARY WIRELINE SHOT THE O.H. FR. 3,789'-3,921' W/A 400 GR. STRING SHOT. RAN A BIT ON 124 JTS. TBG. & TAGGED BTM @ 3,918' FOR 3' OF FILL. PULLED 5 JTS. OF TBG. & LEFT THE BIT SWINGING @ 3,764'. RAN 5 JTS. TBG. & TAGGED UP @ 3,918' FOR 3' OF FILL. BROKE CIRC. & (CONTINUED)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE SR. STAFF ASSISTANT DATE 01-29-97
TYPE OR PRINT NAME TERRY L. HARVEY TELEPHONE NO. 505-393-2144

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

FEB 04 1997