

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Aztec, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.	
30-025-04158	
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	
B-1656-2	
7. Lease Name or Unit Agreement Name	
NORTH MONUMENT G/SA UNIT BLK. 18	
8. Well No.	
11	
9. Pool name or Wildcat	
EUNICE MONUMENT G/SA	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	oil well ☒ gas well ☐ other ☐
2. Name of Operator	AMERADA HESS CORPORATION
3. Address of Operator	POST OFFICE DRAWER D, MONUMENT, NEW MEXICO 88265
4. Well Location	

Unit Letter K : 1980 Feet From The WEST Line and 1980 Feet From The SOUTH Line

Section 2 Township 20S Range 36E N-M-P-M LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
PLUG AND ABANDON ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	COMMENCE DRILLING OPNS. ☐
CHANGE PLANS ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	CASING TEST AND CEMENT JOB ☐
OTHER: Convert to injection well. ☒	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #1811 R-9596

Move in and RU pullint unit, reverse unit and air unit. ND wellhead. TOH and lay down rods and pump. ND wellhead. NU BOP. TOH w/tbg. TIH w/RBP and set at ±500'. Install new wellhead equipment. Retrieve RBP. TIH w/bit, drill collars and tbg. Clean out to TD at 3,912' and deepen openhole to 3,983'. TOH w/bit. TIH w/underreamer, drill collars and tbg. and underream openhole. TOH w/underreamer. RD air unit. RU Schlumberger and log the openhole w/Sonic/LDT/CNL/GR tools. RD Schlumberger. TIH w/a sonic hammer on tbg. to TD. RU acid co. Acidize well w/5,000 gals. 15% NEFE DI HCL w/3% DP-77MX Micellar Solvent. TOH w/sonic hammer. TIH w/tbg. and pkr. Set pkr. at ±3,750'. Swab/flow back load. TOH w/tbg. and pkr., laying down production tbg. Pick up and TIH w/2-3/8" lined injection tbg. w/inj. pkr. ND BOP. NU injection wellhead assembly. RD and move out pulling unit. Clean and clear location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE Sr. Staff Assistant DATE 03-22-95

TYPE OR PRINT NAME Terry L. Harvey TELEPHONE NO. 393-2144

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

MAR 28 1995