

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-04162
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	NORTH MONUMENT G/SA UNIT BLK. 18
8. Well No.	4
9. Pool name or Wildcat	EUNICE MONUMENT G/SA

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator AMERADA HESS CORPORATION
3. Address of Operator POST OFFICE DRAWER D, MONUMENT, NEW MEXICO 88265	4. Well Location Unit Letter <u>D</u> : <u>660</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>WEST</u> Line Section <u>2</u> Township <u>20S</u> Range <u>36E</u> NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>Casing Test. Temporary Abandonment</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

07-05-93 Thru 07-16-93 NMGSAU #1804

X-Pert Well Service rigged up pulling unit. Received 133 jts. 2-7/8" and 8 jts. 2-3/8" tbgs. as work string. Flowed gas from casing and removed 6" 600 tubinghead flange. Installed a 6" 600 manual BOP. TIH with a 3-7/8" drill bit, bit sub, 8 jts. 2-3/8" 10V tbgs. and 125 jts. 2-7/8" 10V tbgs. Tagged liner top at 3,742' and top of fill at 3,927', for 1' of fill in 4-1/2" liner. TOH with 125 jts. 2-7/8" 10V tbgs., 8 jts. 2-3/8" 10V tbgs., bit sub and drill bit. TIH with a 4-1/2" Elder Cast Iron Bridge Plug, setting tool and SN on 8 jts. 2-3/8" tbgs. and 122 jts. 2-7/8" tbgs. Set CIBP at 3,850', pulled setting tool to 3,841' and circulated casing with 120 bbls. fresh water. Pressure tested 6-5/8" casing from 0' to 3,739' and 4-1/2" liner from 3,739' to 3,929'. Pressure decreased from 560 psi to 540 psi in 30 mins. Checked surface-intermediate and intermediate-production casing annuli and found no pressure or flow. Circulated casing with 120 bbls. packer fluid and TOH laying (Continued On Back)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE Staff Assistant DATE 07-16-93  
TYPE OR PRINT NAME Terry L. Harvey TELEPHONE NO. 393-2144

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

This Approval of Temporary  
Abandonment Expires

AUG 13 1993

8-1-98

down 121 jts. 2-7/8" tbg., 8 jts. 2-3/8" tbg., SN and setting tool. Removed 6" 600 manual BOP, loaded casing with packer fluid and installed a 6" 600 tubinghead flange with a 2-7/8" x 4' tbg. sub threaded into bottom of flange half. Cleaned location and rigged down pulling unit.

Temporarily Abandoned.