

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-04165
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	A-1375-39
7. Lease Name or Unit Agreement Name	
NORTH MONUMENT G/SA UNIT BLK. 18	
8. Well No.	1
9. Pool name or Wildcat	
EUNICE MONUMENT G/SA	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>
2. Name of Operator	AMERADA HESS CORPORATION
3. Address of Operator	POST OFFICE DRAWER D, MONUMENT, NEW MEXICO 88265
4. Well Location	

Unit Letter A : 660 Feet From The NORTH Line and 660 Feet From The EAST Line

Section 2 Township 20S Range 36E N.M.P.M. LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  
**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	
OTHER: <u>Convert to injection well.</u> <input checked="" type="checkbox"/>	

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #1801

*R-9596*  
Move in and RU pulling unit, reverse unit and air unit. ND wellhead. TOH and lay down rods and pump. ND wellhead. NU BOP. TOH w/tubing, TIH w/RBP and set  $\pm 500'$ . Install new wellhead equipment. Retrieve RBP. TIH w/bit, drill collars and tbg. Clean out to TD at 3,945'. TOH w/bit. TIH w/underreamer, drill collars and tbg. and underream openhole. TOH w/underreamer. RD air unit. RU Schlumberger and log the openhole w/Sonic/LDT/CNL/GR tools. Evaluate logs for additional perforations. Perforate as needed. RD Schlumberger. TIH w/sonic hammer on tbg. to TD. RU acid co. Acidize well w/5,000 gals. 15% NEFE DI HCL w/3% DP-77MX Micellar Solvent. TOH w/sonic hammer. TIH w/tubing and packer. Set pkr. at  $\pm 3,700'$ . Swab/flow back load. TOH w/tbg. & packer, laying down production tbg. Pick up and TIH w/2-3/8" lined injection tbg. w/injection packer. ND BOP. NU injection wellhead assembly. RD and move out pulling unit. Clean and clear location.

I hereby certify that the information shown is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE Sr. Staff Assistant DATE 03-22-95  
TYPE OR PRINT NAME Terry L. Harvey TELEPHONE NO. 393-2144

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE MAR 28 1995

CONDITIONS OF APPROVAL, IF ANY: