

RECOMMENDED WORK PROCEDURE

LEASE State A WELL NO. 2
 ANNULAR FLUID PRIOR TO WORKOVER oil & water W/O FLUID TO BE USED mud later flow
 WT. (LBS/GAL.) 9.5 ZONE San Andres HYD. PRESS 1900 psi RES. PRESS N/A
 ZONE _____ HYD. PRESS _____ RES. PRESS _____
 ZONE _____ HYD. PRESS _____ RES. PRESS _____
 Contact NMOCC 24 hrs before MIRU @ 373-6161

1. MIRU. ND wellhead. NU BOP. POH w/ 2 7/8" tbg. Lay down perforated sn.
2. RIH w/ 5"-15" CIBP. Set @ $\pm$ 3900'. Cop w/ 35' cmt. POH w/ WL.
3. RIH w/ 2 7/8" tbg open end. Circulate hole w/ 9.5 fls MLE. (140 bbls)
4. Spot 13 sx Class H cmt across liner top (2676'-2776').
5. Spot 17 sx Class H cmt across top of Yates (2420'-2520').
6. Spot 17 sx Class H cmt across top of salt (2030'-2130').
7. Spot 17 sx Class H cmt across surface csg shoe (210'-310').
8. Spot 10 sx Class H cmt @ surface (0'-60').
9. POH w/ tbg. Erect P&A monument.
10. Clean & Clear Location

M.E. Strobel 3-20-86

RECEIVED

MAR 26 1986

Procedure given and approved by PRODUCTION YACETS Waltz
 NMOCC - Hill-