

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN THE
(Other Instructions
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ <i>water injection well</i>		6. LEASE DESIGNATION AND SERIAL NO. <i>1.C. 030127 (2)</i>	
2. NAME OF OPERATOR <i>Continental Oil Company</i>		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR <i>P. O. Box 480, Hobbs, New Mexico 88240</i>		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <i>660' FSL & WL of Sec. 3, T-20S, R-36E, Lea County, N. Mex.</i>		8. FARM OR LEASE NAME <i>Bedford Union Unit</i>	
14. PERMIT NO.		9. WELL NO. <i>19</i>	
15. ELEVATIONS (Show whether DF, RT, CR, etc.) <i>3626' DF</i>		10. FIELD AND POOL, OR WILDCAT <i>Cummins Pool</i>	
		11. SEC., T., R., M., OR B.R. AND SURVEY OR AREA <i>Sec. 3, T-20S, R-36E</i>	
		12. COUNTY OR PARISH <i>Lea</i>	
		13. STATE <i>N. Mex.</i>	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	
(Other) <i>Plug Back</i>	☒	(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

In order to get better waterflood coverage, it is proposed to plug back this well by the following procedure:

Run CIBP on wire line and set at 3990'. Cap CIBP with one sack cement. Re-run cement lined tubing with packer and set packer at 3708'.

This CIBP will stop water from being injected into the perms from 3999' to 3960' and from 3972' to 3986'.

US 45-5 Chew mid-2 Perm Perm-Hobbs? Jth. Res 2. 7th

I hereby certify that the foregoing is true and correct

SIGNED *M. E. Yeakley*

TITLE *Administrative Section Chief*

DATE *1-3-68*

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

JAN 6 1968

A. R. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side