N. M. OIL CONS. COMMISSION

Form Approved. Form 9-331 Budget Bureau No. 42-R1424 P. O. BOX 1980 Dec. 1973 UNITED STATES HOBBS, NEW MEXICO 584248 LC-031622 DEPARTMENT OF THE INTERIOR 6. IF INDIAN, ALLOTTEE OR TRIBE NAME **GEOLOGICAL SURVEY** 7. UNIT AGREEMENT NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) well 💢 9. WELL NO. other well 2. NAME OF OPERATOR 10. FIELD OR WILDCAT NAME CONOCO INC. Eunice Monument 3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, N.M. 88240 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 Sec. 10, T-205, R-36E AT SURFACE: 660 FNL \$330 FEL 12. COUNTY OR PARISH 13. STATE AT TOP PROD. INTERVAL AT TOTAL DEPTH: 14. API NO. 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, 15. ELEVATIONS (SHOW DF, KDB, AND WD) REPORT, OR OTHER DATA SUBSEQUENT REPORT OF: REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE (NOTE: Report results of multiple completion or zone REPAIR WELL change on Form 9-330.) PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* MIRU 3/4/82. Perbw/ ZJSPF 3478, 49,50,51,52,53,54,55,56. String shot OH 3805'-3895'. Acidize OH w/1220 gals. 15% HCL-NE-FE. Acidize 3748'-57'w/2775 gals. 15% HCL-NE-FE. CO'Lto 3900: Tested 4/15/82: 1 BOPD, 170 BWPD, 8MCFPD Set @ __ Subsurface Safety Valve: Manu. and Type _ 18. I hereby pertify that the foregoing is true and correct 4.5. Administrative Supervisor DATE SIGNED A (This space for Federal or State office use) **ACCEPTED FOR RECORD** DATE CONDITIONS OF APPROVAL FAN. W. CHESTER

JUL 1 4 1982

U.S. GEOLOGICAL SURVEY Instructions on Reverse Side