UNITED STATES

		Budget Bureau No. 42-R1424
LEASE		
	4/44	1.54

DEPARTMENT OF THE INTERIOR	
	NM 1/50
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
	NMFU.
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas well other JUN 2 9	Sanderson B-1
	9. WELL NO.
2. NAME OF OPERATOR	4
CONOCO INC. U.S. GEAR LORDAN ON THIS	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, N.M. 88240	Eumont Yates Seven Pivers Queen
P. O. Box 400, Hobbs, N.M. 85240	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17	AREA
helow)	Sea 10 T- 205 P 21 C
AT SURFACE: 990'FSL & 330'FEL	Sec. 10, T-205, R-36E 12. COUNTY OR PARISH :: 3. STATE
AT TOP PROD. INTERVAL:	
AT TOTAL DEPTH:	Lea NM
	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	(6.001, 27, 108, 110, 110)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF 🗌	
FRACTURE TREAT	
SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING 🗌	charige on Form 9-33().) -
MULTIPLE COMPLETE	
CHANGE ZONES	
ABANDON*	
(other)	
17 DECORATE PROPERTY OF AN ANALYSIS AND ANALYSIS ANALYSIS AND ANALYSIS ANALYSIS AND ANALYSIS AND ANALYSIS AND ANALYSIS AND ANALYSIS ANALYSIS ANALYSIS ANALYSIS ANALYSIS ANALYSIS ANALYSIS ANALYSIS ANALY	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state	all pertinent details, and give pertinent dates,
including estimated date of starting any proposed work. If well is di	rectionally drilled give subsurface locations and
including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinen	rectionally drilled, give subsurface locations and t to this work.)*
including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinen	rectionally drilled, give subsurface locations and t to this work.)*
measured and true vertical depths for all markers and zones pertinent MIRU 5/5/81. CO to 3864 KB. Perb 3840-44, 24-33/	rectionally drilled, give subsurface locations and to this work.)* 3800'-15', 3750'-65'w/2 JSPF. Sef
measured and true vertical depths for all markers and zones pertinent MIRU 5/5/81. CO to 3864 KB. Perb 3840-44, 24-33/	rectionally drilled, give subsurface locations and to this work.)* 3800'-15', 3750'-65'w/2 JSPF. Sef
measured and true vertical depths for all markers and zones pertinent MIRU 5/5/81. CO to 3864 KB. Perb 3840-44, 24-33/ pkr at 3718. Acidize of 6300 gals 15% HCL-NE-FE. Fl	rectionally drilled, give subsurface locations and to this work.)* 3800'-15', 3750'-65'w'2 JSPF. Set (ush w/15bbls. 10ppg Srine. Swab.
measured and true vertical depths for all markers and zones pertinent MIRU 5/5/81. CO to 3864 KB. Perb 3840-44, 24-33/ pkr at 3718. Acidize of 6300 gals 15% HCL-NE-FE. Fl	rectionally drilled, give subsurface locations and to this work.)* 3800'-15', 3750'-65'w'2 JSPF. Set (ush w/15bbls. 10ppg Srine. Swab.
measured and true vertical depths for all markers and zones pertinent MIRU 5/5/81. CO to 3864 KB. Perb 3840-44, 24-33/	rectionally drilled, give subsurface locations and to this work.)* 3800'-15', 3750'-65'w'2 JSPF. Set (ush w/15bbls. 10ppg Srine. Swab.
measured and true vertical depths for all markers and zones pertinent MIRU 5/5/81. CO to 3864'KB. Perb 3840'-44, 24'-33', pkr at 3718' Acidize of 6300 gals 15% HCL-NE-FE. Fl Scale squeeze of 2 drums chemical in 2066s 10	rectionally drilled, give subsurface locations and to this work.)* 3800'-15', 3750'-65'w/2JSPF. Set with w/15bbls. 10ppg brine. Swab. opg brine. Hush w/218bbls. 10ppg
measured and true vertical depths for all markers and zones pertinent MIRU 5/5/81. CO to 3864'KB. Perb 3840'-44, 24'-33', pkr at 3718' Acidize of 6300 gals 15% HCL-NE-FE. Fl Scale squeeze of 2 drums chemical in 2066s 10	rectionally drilled, give subsurface locations and to this work.)* 3800'-15', 3750'-65'w/2JSPF. Set with w/15bbls. 10ppg brine. Swab. opg brine. Hush w/218bbls. 10ppg
measured and true vertical depths for all markers and zones pertinent MIRU 5/5/81. CO to 3864 KB. Perb 3840-44, 24-33/ pkr at 3718. Acidize of 6300 gals 15% HCL-NE-FE. Fl	rectionally drilled, give subsurface locations and to this work.)* 3800'-15', 3750'-65'w/2JSPF. Set with w/15bbls. 10ppg brine. Swab. opg brine. Hush w/218bbls. 10ppg
measured and true vertical depths for all markers and zones pertinent MIRU 5/5/81. CO to 3864'KB. Perb 3840'-44, 24'-33', pkr at 3718' Acidize of 6300 gals 15% HCL-NE-FE. Fl Scale squeeze of 2 drums chemical in 2066s 10	rectionally drilled, give subsurface locations and to this work.)* 3800'-15', 3750'-65'w/2JSPF. Set with w/15bbls. 10ppg brine. Swab. opg brine. Hush w/218bbls. 10ppg
measured and true vertical depths for all markers and zones pertinent MIRU 5/5/81. CO to 3864'KB. Perb 3840'-44, 24'-33', pkr at 3718' Acidize of 6300 gals 15% HCL-NE-FE. Fl Scale squeeze of 2 drums chemical in 2066s 10	rectionally drilled, give subsurface locations and to this work.)* 3800'-15', 3750'-65'w/2JSPF. Set with w/15bbls. 10ppg brine. Swab. opg brine. Hush w/218bbls. 10ppg
measured and true vertical depths for all markers and zones pertinent MIRU 5/5/81. CO to 3864'KB. Perb 3840'-44, 24'-33', pkr at 3718' Acidize of 6300 gals 15% HCL-NE-FE. Fl Scale squeeze of 2 drums chemical in 2066s 10	rectionally drilled, give subsurface locations and to this work.)* 3800'-15', 3750'-65'w/2JSPF. Set with w/15bbls. 10ppg brine. Swab. opg brine. Hush w/218bbls. 10ppg
measured and true vertical depths for all markers and zones pertinent MIRU 5/5/81. CO to 3864'KB. Perb 3840'-44, 24'-33', pkr at 3718' Acidize of 6300 gals 15% HCL-NE-FE. Fl Scale squeeze of 2 drums chemical in 2066s 10	rectionally drilled, give subsurface locations and to this work.)* 3800'-15', 3750'-65'w/2JSPF. Set with w/15bbls. 10ppg brine. Swab. opg brine. Hush w/218bbls. 10ppg
including estimated date of starting any proposed work. If well is dismeasured and true vertical depths for all markers and zones pertinent. MIRU 5/5/81. CO to 3864'KB. Perb 3840'-44, 24'-33', phrat 3718' Acidize of 6300 gals 15% HCL-NE-FE. Fl. Scale squeeze of 2 drums chemical in 2066/s 10, brine. Ran production equipment. Tested on 5/29/s	rectionally drilled, give subsurface locations and to this work.)* 3800'-15', 3750'-65'w/2JSPF. Set with w/15 bbls. 10 ppg brine. Swab. opg brine. Flush w/218bbls. 10ppg 31: 5B0, 18BW, 51 MCF.
including estimated date of starting any proposed work. If well is dismeasured and true vertical depths for all markers and zones pertinent. MIRU 5/5/81. CO to 3864'KB. Perb 3840'-44, 24'-33', phrat 3718' Acidize of 6300 gals 15% HCL-NE-FE. Fl. Scale squeeze of 2 drums chemical in 2066/s 10, brine. Ran production equipment. Tested on 5/29/s	rectionally drilled, give subsurface locations and to this work.)* 3800'-15', 3750'-65'w/2JSPF. Set with w/15 bbls. 10 ppg brine. Swab. opg brine. Flush w/218bbls. 10ppg 31: 5B0, 18BW, 51 MCF.
including estimated date of starting any proposed work. If well is dismeasured and true vertical depths for all markers and zones pertinent. MIRU 5/5/81. CO to 3864'KB. Perb 3840'-44, 24'-33', phrat 3718' Acidize of 6300 gals 15% HCL-NE-FE. Fl. Scale squeeze of 2 drums chemical in 2066/s 10, brine. Ran production equipment. Tested on 5/29/s	rectionally drilled, give subsurface locations and to this work.)* 3800'-15', 3750'-65'w/2JSPF. Set with w/15 bbls. 10 ppg brine. Swab. opg brine. Flush w/218bbls. 10ppg 31: 5B0, 18BW, 51 MCF.
including estimated date of starting any proposed work. If well is dismeasured and true vertical depths for all markers and zones pertinent. MIRU 5/5/81. CO to 3864'KB. Perb 3840'-44, 24'-33', pkr at 3718' Acidize of 6300 gals 15% HCL-NE-FE. Fl. Scale squeeze of 2 drums chemical in 2066s 10, brine. Ran production equipment. Tested on 5/29/8	rectionally drilled, give subsurface locations and to this work.)* 3800'-15', 3750'-65'w/2JSPF. Set with w/15 bbls. 10 ppg brine. Swab. opg brine. Flush w/218bbls. 10ppg 31: 5B0, 18BW, 51 MCF.
including estimated date of starting any proposed work. If well is dismeasured and true vertical depths for all markers and zones pertinent. MIRU 5/5/81. CO to 3864'KB. Perb 3840'-44, 24'-33', pkr at 3718' Acidize of 6300 gals 15% HCL-NE-FE. Fl. Scale squeeze of 2 drums chemical in 2066s 10, brine. Ran production equipment. Tested on 5/29/8 Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct	rectionally drilled, give subsurface locations and to this work.)* 3800'-15', 3750'-65'w/2JSPF. Set (ush w/15bbls.10ppg brine. Swab. opg brine. Hush w/218bbls.10ppg 31: 5B0, 18BW, 51MCF. Set @Ft.
including estimated date of starting any proposed work. If well is dismeasured and true vertical depths for all markers and zones pertinent. MIRU 5/5/81. CO to 3864'KB. Perb 3840'-44, 24'-33', pkr at 3718' Acidize of 6300 gals 15% HCL-NE-FE. Fl. Scale squeeze of 2 drums chemical in 2066s 10, brine. Ran production equipment. Tested on 5/29/8 Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct	rectionally drilled, give subsurface locations and to this work.)* 3800'-15', 3750'-65'w/2JSPF. Set (ush w/15bbls.10ppg brine. Swab. opg brine. Hush w/218bbls.10ppg 31: 5B0, 18BW, 51MCF. Set @Ft.
including estimated date of starting any proposed work. If well is dismeasured and true vertical depths for all markers and zones pertinent. MIRU 5/5/81. CO to 3864'KB. Perb 3840'-44, 24'-33', pkr at 3718' Acidize of 6300 gals 15% HCL-NE-FE. Fl. Scale squeeze of 2 drums chemical in 2066/s 10, brine. Ran production equipment. Tested on 5/29/s Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct SIGNED Was A. Junta Land Type Title Administrative Supervisored	rectionally drilled, give subsurface locations and to this work.)* 3800'-15', 3750'-65'w/2JSPF. Set with w/15bbls. 10ppg brine. Swab. Opg brine. Flush w/218bbls. 10ppg 31: 5B0, 18BW, 51MCF. Set @Ft.
including estimated date of starting any proposed work. If well is dismeasured and true vertical depths for all markers and zones pertinent. MIRU 5/5/81. CO to 3864'KB. Perf 3840'-44, 24'-33', pkr at 3718' Acidize of 6300 gals 15% HCL-NE-FE. Fl. Scale squeeze of 2 drums chemical in 2066s 10, brine. Ran production equipment. Tested on 5/29/8 Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct SIGNED WAR - Administrative Supervisional Confect of the composition of the	rectionally drilled, give subsurface locations and to this work.)* 3800'-15', 3750'-65'w/2JSPF. Set with w/15bbls. 10ppg brine. Swab. Opg brine. Flush w/218bbls. 10ppg 31: 5B0, 18BW, 51MCF. Set @Ft.
including estimated date of starting any proposed work. If well is dismeasured and true vertical depths for all markers and zones pertinent. MIRU 5/5/81. CO to 3864'KB. Perf 3840'-44, 24'-33', pkr at 3718'. Acidize of 6300 gals 15% HCL-NE-FE. Fl. Scale squeeze of 2 drums chemical in 2066/s 10, brine. Ran production equipment. Tested on 5/29/s Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct SIGNED War A. Thereby Supervision of the contract of the c	rectionally drilled, give subsurface locations and to this work.)* 3800'-15', 3750'-65'w', 2JSPF. Seffush w/15bbls. 10ppg Srine. Swab. Sepg brine. Flush w/218bbls. 10ppg B1: 5B0, 18BW, 51MCF. Set @Ft. Sor DATE June 26, 1981
including estimated date of starting any proposed work. If well is dismeasured and true vertical depths for all markers and zones pertinent. MIRU 5/5/81. CO to 3864'KB. Perf 3840'-44, 24'-33', pkr at 3718'. Acidize of 6300 gals 15% HCL-NE-FE. Fl. Scale squeeze of 2 drums chemical in 2066/s 10, brine. Ran production equipment. Tested on 5/29/s Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct SIGNED War A. Thereby Supervision of the contract of the c	rectionally drilled, give subsurface locations and to this work.)* 3800'-15', 3750'-65'w/2JSPF. Set with w/15bbls. 10ppg brine. Swab. Opg brine. Flush w/218bbls. 10ppg 31: 5B0, 18BW, 51MCF. Set @Ft.
including estimated date of starting any proposed work. If well is dismeasured and true vertical depths for all markers and zones pertinent. MIRU 5/5/81. CO to 3864'KB. Perf 3840'-44, 24'-33', pkr at 3718'. Acidize of 6300 gals 15% HCL-NE-FE. Fl. Scale squeeze of 2 drums chemical in 2066/s 10, brine. Ran production equipment. Tested on 5/29/s Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct SIGNED War A. Thereby Supervision of the contract of the c	rectionally drilled, give subsurface locations and to this work.)* 3800'-15', 3750'-65'w', 2JSPF. Seffush w/15bbls. 10ppg Srine. Swab. Sepg brine. Flush w/218bbls. 10ppg B1: 5B0, 18BW, 51MCF. Set @Ft. Sor DATE June 26, 1981
including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinent. MIRU 5/5/81. CO to 3864 KB. Perf 3840-44, 24-33/pkr at 3718. Acidize w/ 6300 gals 15% HCL-NE-FE. Fl. Scale squeeze w/ 2 drums chemical in 2066/s 10/pbrine. Ran production equipment. Tested on 5/29/s Drine. Ran production equipment. Tested on 5/29/s 18. I hereby certify that the foregoing is true and correct SIGNED WAR - WAR ALLE ANSIGNED FOR RECORDED for Federal or State office ACCEPTED FOR RECORDED for Federal or State office PETER W. CHENTER TITLE	rectionally drilled, give subsurface locations and to this work.)* 3800'-15', 3750'-65'w', 2JSPF. Seffush w/15bbls. 10ppg Srine. Swab. Sepg brine. Flush w/218bbls. 10ppg B1: 5B0, 18BW, 51MCF. Set @Ft. Sor DATE June 26, 1981
Subsurface Safety Valve: Manu. and Type The Administrative Supervise ACCEPTED FOR RECORDED to TITLE Administrative Supervise ACCEPTED FOR RECORDED to TITLE ACCEPTED TO THE TIT	rectionally drilled, give subsurface locations and to this work.)* 3800'-15', 3750'-65'w', 2JSPF. Seffush w/15bbls. 10ppg Srine. Swab. Sepg brine. Flush w/218bbls. 10ppg B1: 5B0, 18BW, 51MCF. Set @Ft. Sor DATE June 26, 1981
including estimated date of starting any proposed work. If well is dismeasured and true vertical depths for all markers and zones pertinent. MIRU 5/5/81. CO to 3864'KB. Perf 3840'-44, 24'-33', pkr at 3718'. Acidize of 6300 gals 15% HCL-NE-FE. Fl. Scale squeeze of 2 drums chemical in 2066/s 10, brine. Ran production equipment. Tested on 5/29/s Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct SIGNED War A. Thereby Supervision of the contract of the c	set @ Ft. Set @ Ft. DATE