

COPY TO O. C. C.
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

<p>1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER</p> <p>2. NAME OF OPERATOR <u>Amerada Hess Corporation</u></p> <p>3. ADDRESS OF OPERATOR <u>Drawer D, Monument, New Mexico 88265</u></p> <p>4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <u>1980' FNL & 660' FEL</u></p> <p>14. PERMIT NO.</p>		<p>5. LEASE DESIGNATION AND SERIAL NO. <u>LC 046164 (a)</u></p> <p>6. IF INDIAN, ALLOTTEE OR TRIBE NAME</p> <p>7. UNIT AGREEMENT NAME</p> <p>8. FARM OR LEASE NAME <u>H. W. Andrews</u></p> <p>9. WELL NO. <u>3</u></p> <p>10. FIELD AND POOL, OR WILDCAT <u>Eunice-Monument G/SA</u></p> <p>11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec. 11, T20S, R36E</u></p> <p>12. COUNTY OR PARISH <u>Lea</u></p> <p>13. STATE <u>New Mexico</u></p>
<p>15. ELEVATIONS (Show whether DF, RT, GR, etc.) <u>3574'</u></p>		

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
(Other)	<input type="checkbox"/>	(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plan to pull rods & pump, check for fill and clean out if necessary. Run pkr. & tbg., set pkr. and acidize Grayburg San Andres zone thru 6-5/8" csg. perf. fr. 3753' to 3799' and in open hole fr. 3803' to 3890' w/20% NE-FE acid, swab load, re-run production equipment and resume production.

RECEIVED


DEC 17 1979

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED E. S. Disher TITLE Supv. Adm. Ser. DATE 12-13-79

(This space for Federal or State office use)



TITLE _____ DATE _____

*See Instructions on Reverse Side