Form 9 (May 1)	0.00	UNIT STATES SUBMIT IN TRIPLIC? DEPARTMENT UF THE INTERIOR (Other instructions on verse side) GEOLOGICAL SURVEY		Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO. LC - 046164 (a)		
<u></u>	SUNDRY (Do not use this form for Use "A	NOTICES AND REPORTS C proposals to drill or to deepen or plug b PPLICATION FOR PERMIT—" for such pr	DN WELLS back to a different reservoir. roposals.)	6. IF INDIAN, ALLOTTE	E OR TRIBE NAME	
1. OIL WEI		CHER		7. UNIT AGREEMENT NA	31N	
	ME OF OPERATOR			8. FARM OR LEASE NAME		
	Amerada Hess Corporation			H.W. Andrews		
	DRESS OF OPERATOR			9. WELL NO.		
		ument, New Mexico 88265		3		
4. LOC See	cation of WELL (Report lo a also space 17 below.) surface 1980 ⁹ FNL & 660	cation clearly and in accordance with any	State requirements.•	10. FIELD AND POOL, O Eunice-Monumer 11. SEC., T. B., M., OB SUBVEY OF AREA SEC. 11, T-20-S,	nt (G-SA)	
14. PE	RMIT NO.	15. BLEVATIONS (Show whether DE	r, RT, GR, etc.)	12, COUNTY OR PARISH	I 13. STATE	
		3574 t DF		Lea	New Mexico	
16.	Che	eck Appropriate Box To Indicate N	Nature of Notice, Report, o	r Other Data		
	NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:		
T	EST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING		
F.	BACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING C		
. 8	HOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANUONME		
R	EPAIR WELL	CHANGE PLANS	(Other)	ulta of multiple completion	on Well	
((Other) Perforate X		(Norg: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			
17. DE	SCRIBE PROPOSED OR COMPL	ETED OPERATIONS (Clearly state all pertine	it details, and give pertinent da	tes, including estimated da	te of starting any	

÷.,

17. DESCRIBE IROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including commuted date of stating and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Pull production. Perforate OH 3813*, 3842*, 3846*, 3852*, 3854*, 3856*, 3858* and 3860* with open hole charges. Perforate 6-5/8" casing at 3753*, 3760*, 3766*, 3772*, 3777*, 3782*, 3792*, 3798* and 3799* with 2 shots per ft. Acidize with 1500 gals. suspending type acid in three equal stages using benzoic acid flakes and graded rock salt as diverter. Swab back acid water. Rerun production equipment and resume production.

Verbal approval from Mr. A.R. Brown 10-18-72.

SIGNED Certify that the foregoing is true and correct	TITLE Aupver., Admin. Services	10-18-72
(This space for Federal or State office use)	TOPROVI	
APPROVED BY CONDITIONS OF APPROVAL, IF ANY :	TITLE 0072 1972	<u>**</u>
*\$a	e Instructions on Reverse SideDistrict incincer	

REDENED

(., 2:1072

OIL CONSENSATION COMM. HOBES, N. M.