

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instruction
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

046164-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

H. W. Andrews

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Monument Grayburg
San Angelo

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 11, T-20-S,
R-36-E

12. COUNTY OR PARISH

Lee

13. STATE

New Mex.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		AUG 2 11 15 AM '66	
2. NAME OF OPERATOR Amerada Petroleum Corporation			
3. ADDRESS OF OPERATOR P. O. Box 668 - Hobbs, New Mexico			
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit letter "H", 1980 feet from the North line & 660 feet from the East line, Section 11, Township 20 South, Range 36 East, NMPM			
14. PERMIT NO. Hazel Wolff Andrews-Permit		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3574' DF	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☒

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We propose to start the following work 8-1-66.

Pull rods, pump & tubing. Run Gamma Ray Neutron Log from surface to TD with Detail from 3000' to TD. Run tubing & packer. Run string shot of 300 & 500 grains in open hole from 3803' to 3888'. Acidize with 1000 gals. 15% HCl acid. Swab back acid water. Mix 15 bbls. formation water with 55 gals. Jet-Cote 60-2, displace into formation & overflush with 30 bbls. lease crude. Pull tubing & packer. Run tubing, pump & rods & resume production.

18. I hereby certify that the foregoing is true and correct

SIGNED

B. D. Siny

TITLE District Superintendent

DATE 7-29-66


(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

*See Instructions on Reverse Side



Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.