

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-04215

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil / Gas Lease No.

7. Lease Name or Unit Agreement Name

EUNICE MONUMENT SOUTH UNIT

8. Well No.

866

9. Pool Name or Wildcat

GRAYBURG SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER INJECTION

2. Name of Operator

CHEVRON USA INC

3. Address of Operator

15 SMITH ROAD, MIDLAND, TX 79705

4. Well Location

Unit Letter O : 990 Feet From The SOUTH Line and 1650 Feet From The EAST Line

Section 11 Township 20S Range 36E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3566' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒

ALTERING CASING ☐

COMMENCE DRILLING OPERATION ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

RE-ACTIVATE INJECTOR ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-15-02: MIRU. NDWH. PUMP 18 BBLS DN CSG. PRESS UP TO 500 PSI. MOVE PKR TO 3582. REL PKR. TAG BRIDGES & BREAK THRU @ 3832 & 3885. TAG TD @ 3891.

4-16-02: TIH W/BIT & CSG SCRAPER TO 3770. TIH W/PKR & PLUG TO 3595. SET PLUG @ 3595. TEST TO 560#. MOVE PKR TO 3590. MOVE PKR TO 3626. SET PLUG @ 3230 & PKR @ 3215. TEST TOOLS TO 550#. REL PKR. TEST CSG. TIH W/PKR TO 3215. PUH TO 3205. SET PKR.

4-17-02: SET PKR @ 3484. PLUG @ 3596. PUH & SET PKR @ 3365.

4-18-02: TIH TO 3596. LATCH ONTO RBP. PERF 3700-3760, 3674-3684 & 3652-3660.

4-19-02: PU SONIC HAMMER & TIH TO 3700. ACID WASH GRAYBURG 3700-3760, 3674-3684, & 3652-3660 W/3600 GALS 7 1/2% HCL. DROP SAND TO PLUG BACK FR TD TO 3820.

4-22-02: TAG SAND FILL @ 3778. C/O FILL TO 3820. DUMP BAIL 10' CMT ON TOP OF SAND. PBTD @ 3810.

4-23-02: TIH & SET PKRS. DISPL W/INHIB 2% KCL. TEST BACKSIDE TO 500 PSI. RUN PRESSURE CHART @ 460 PSI FOR 18 MIN - OK. (CHART ATTACHED) HOOK UP INJECTION LINE.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Denise Leake

TITLE Regulatory Specialist

DATE 6/4/2002

Telephone No. 915-687-7375

TYPE OR PRINT NAME

Denise Leake

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ORIGINAL SIGNED BY
PAUL F. KAUTZ
PETROLEUM ENGINEER

DATE

JUN 06 2002

DeSoto/Nichols 12-93 ver 1.0

5
L
S

