

1 MINERAL OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below:

REPORT ON BEGINNING DRILLING OPERATIONS	X	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL			

Hobbs, N. Mex.

Place

Sept. 16, 1936

Date

OIL CONSERVATION COMMISSION,
Santa Fe, New Mexico.

Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the _____

Repollo Oil Company M. J. Byrd Well No. 2 in the _____
Company or Operator Lease
SE/4 of NE/4 of Sec. 11, T. 20S, R. 36E, N. M. P. M.,
Monument Field, Lea County.

The dates of this work were as follows: 9/16/36

Notice of intention to do the work was [was not] submitted on Form C-102 on _____ 19____
and approval of the proposed plan was [was not] obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Commenced Drilling September 16, 1936

Witnessed by Ray Hamilton Amerada Oil Co.
Name Company Title

Subscribed and sworn to before e this 22

day of Sept., 1936

I hereby swear or affirm that the information given above is true and correct.

Name R. Smith

Position Dist. Supt.

Representing Repollo Oil Co
Company or Operator

Address Hobbs, N. Mex.

My Commission expires 12-3-38

Notary Public

Remarks:

APPROVED

[Signature]
Name

Oil & Gas Inspector
Title

110

REPORT OF THE BOARD OF SURGEONS

The following report is submitted to the Surgeon General of the Army, Department of the Army, Washington, D. C., for his information and guidance. It is based on the findings of the Board of Surgeons, which was organized on 10 October 1964, to investigate the circumstances surrounding the death of Captain James Earl Ray, Jr., who was killed in action on 10 October 1964, while serving with the 1st Cavalry Division, Vietnam.

Summary of Report by Board of Surgeons

The Board of Surgeons, composed of the Surgeon General, the Surgeon, the Chief of Staff, and the Adjutant General, met on 10 October 1964, to discuss the findings of the investigation. The Board concluded that the death of Captain Ray was the result of a friendly fire incident, and that the circumstances surrounding the incident were such that the Board was unable to determine the exact cause of the death.

The Board recommended that the following actions be taken: (1) The investigation be continued to determine the exact cause of the death; (2) The Board be authorized to conduct a full-scale investigation of the incident; (3) The Board be authorized to recommend appropriate disciplinary action against the personnel involved in the incident.

Very truly yours,
Surgeon General

The following is a summary of the findings of the investigation. The Board concluded that the death of Captain Ray was the result of a friendly fire incident, and that the circumstances surrounding the incident were such that the Board was unable to determine the exact cause of the death.

The Board recommended that the following actions be taken: (1) The investigation be continued to determine the exact cause of the death; (2) The Board be authorized to conduct a full-scale investigation of the incident; (3) The Board be authorized to recommend appropriate disciplinary action against the personnel involved in the incident.

DETAILS OF THE CASE AND RECOMMENDATIONS

The following is a summary of the details of the case and the recommendations of the Board.

The Board concluded that the death of Captain Ray was the result of a friendly fire incident, and that the circumstances surrounding the incident were such that the Board was unable to determine the exact cause of the death.

The Board recommended that the following actions be taken: (1) The investigation be continued to determine the exact cause of the death; (2) The Board be authorized to conduct a full-scale investigation of the incident; (3) The Board be authorized to recommend appropriate disciplinary action against the personnel involved in the incident.

The following is a summary of the details of the case and the recommendations of the Board.

The Board concluded that the death of Captain Ray was the result of a friendly fire incident, and that the circumstances surrounding the incident were such that the Board was unable to determine the exact cause of the death.

The Board recommended that the following actions be taken: (1) The investigation be continued to determine the exact cause of the death; (2) The Board be authorized to conduct a full-scale investigation of the incident; (3) The Board be authorized to recommend appropriate disciplinary action against the personnel involved in the incident.

The following is a summary of the details of the case and the recommendations of the Board.

The Board concluded that the death of Captain Ray was the result of a friendly fire incident, and that the circumstances surrounding the incident were such that the Board was unable to determine the exact cause of the death.