## ENERGY AND MINERALS DEPARTMENT

SIMIC OF HER POSTU

		_
DISTRIBUTION		
SANTA PE	Ŀ	
FILE		
V.S.G.S.	<del> </del>	<u> </u>
LAND OFFICE	<del>-</del>	

## OIL CONSERVATION DIVISION P. O. BOX 2088 SANTA FE, NEW MEXICO 87501

Form	¢-	10	3		
Revis				٠.	•

V.S.G.S.	Sa. Indicate Type of Lease
LAND OFFICE	State Oil & Gas Lease No.
SPERATOR	S-NM-56
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRIVE ON TO DEEPEN OF PLUG BACK TO A DIFFERENT RESERVOIR.	7. Unit Agreement Name
OIL X SAS WELL OTHER-	8. Form or Lease Name
ARCO Oil and Gas Company	William P. Byrd
P.O. Box 1610, Midland, Texas 79702	9. Well No.
4. Location of Well	10. Field and Pool, or Wildcat
West LINE, SECTION 11 TOWNSHIP 20S RANGE 36E	Eunice Monument GBSA
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
Check Appropriate Box To Indicate Nature of Notice, Report or	Other Data
	ENT REPORT OF:
PERFORM REMEDIAL WORK PLUS AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ASANDON COMMENCE ORILLING OPHS.	PLUS AND ASAHOOMMENT
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JQS	
Add perfs to same zone & treat	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclu-	ding estimated date of starting any proposes
work) SEE RULE 1703.	
Propose to add perf & treat as follows:	
1. Kill well. POH w/CA.	
2. CO to PBD 3860.	
3. Set RBP at 3822 & press test csg to 500#.	
4. Re-perf Gb SA f/3842 - 3833. Perf Gb SA f/3832 - 3824	<b>+</b> •
<ul><li>5. Acidize w/3500 gals.</li><li>6. Swab test.</li></ul>	
7. RIH w/CA.	
8. Return to production.	
	•
	•
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
Engr. Tech. 915-688-5672	08/08/88
	MAYE
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR	AUG 1 2'88