STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

DISTRIBUTION		
BANTA FE		ĺ
FILE		1
U.S.G.S.	1	Ţ.
LAND OFFICE	1	
OPERATOR	T T	

OIL CONSERVATION DIVISION DISTRIBUTION P. O. BOX 2088 SANTA FE SANTA FE, NEW MEXICO 87501	Form C-103 Revised 10-1-75
U.S.G.S. LANC OFFICE OPERATOR	Sa. Indicate Type of Lease State X Fee 5. State Off & Gas Lease No. B-1398
SUNDRY NOTICES AND REPORTS ON WELLS	
GIL X GAR OTHER-	7. Unit Agreement Name
SHELL WESTERN E&P INC.	8. Fatm or Lease Name STATE E
P.O. BOX 991, HOUSTON, TEXAS 77001	9. Well No. 2 10. Field and Pool, or Wildcat
Location of Well WHIT LETTER D . 660 FEET FROM THE NORTH LINE AND 660 FEET FROM	FUNICE MONUMENT (C_SA)
THE WEST LINE, SECTION 13 TOWNSHIP 20-S RANGE 36-E NAPE	
15. Elevation (Show whether DF, RT, GR, etc.) 3559 DF	12. County LEA
Check Appropriate Box To Indicate Nature of Notice, Report or On Notice of Intention to: Subsequent	ther Data T REPORT OF:
PLUC AND ABANDON REMEDIAL WORK COMMENCE DRILLING DENS. CHANGE PLANS CASING TEST AND CEMENT JOB OTHER TEMPORARY ABANDONMENT	ALTERING CASING PLUG AND ABANDONMENT
7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includin work) SEE RULE 1703. WELL TEMPORARILY ABANDONED BY PULLING PRODUCTION EQUIPMENT AS REPORTE FEBRUARY 2, 1956. WE WISH TO EXTEND THIS WELL'S TA'D STATUS FOR ONE BEING EVALUATED IN A GRAYBURG WATERFLOOD STUDY AND FOR UPHOLE POTENTI ERLY TEMPORARILY ABANDON AS FOLLOWS:	D ON FORM C-103 APPROVED YEAR AS THIS WELLBORE IS
 Run gauge ring and junk basket to 3600'35' Set a CIBP @ 3550' and cap w/2 sx cmt (20' minimum). Circulate inhibited water, test casing to 300 psi, and temporaril 	y abandon.

8.1 hereby certify that the information above is true and complete to the best of my knowledge and belief. SUPERVISOR REG. & PERMITTING MARCH 1, 1985 ORIGINAL SIGNED BY JERRY SEXTON MAR - 5 1985 DISTRICT I SUPERVISOR