

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well ☐ Oil Well ☒ Gas Well ☐ Other	5. Lease Designation and Serial No. LC-031622A
2. Name of Operator Conoco Inc.	6. If Indian, Allottee or Tribe Name
3. Address and Telephone No. 10 West Dr. W. Midland TX 686-6553	7. If Unit or CA, Agreement Designation
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1650 FNL & 1650 FEL Unit Letter G, Sect. 14, T20S, 36E	8. Well Name and No. Sanderson A No. 13
	9. API Well No. 30-025-04267
	10. Field and Pool, or Exploratory Area Eumont Queen Bar
	11. Country or Parish, State Lea

CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☒ Altering Casing
☒ Other Squeeze Queen Perfs
- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1-9-91 POH w/ 2 3/4" buttress tbg, GIH w/ 5 1/2" scraper & 2 3/8" tbg. Ran scraper to 3630. POH.
1-10-91 GIH w/ 5 1/2" RBP, pkr. & 2 3/8" tbg. Set RBP at 3595 & tst RBP-OK. Spot 25x sand on RBP. Pull pkr up hole to 3345. Pres. up backside to 500#. Squeeze Queen perfs (3450-3545) w/ 100 sks class "C" cmt w/ .690 FLA & 290 CaCL, followed by 100 sks class "C" w/ 290 CaCL. Pres up to 1200# - HELD. Reverse out 30 sk cmt.
1-11-91 Pres tst osq to 500# for 40 min. No pres drop. GIH w/ 4 3/4" bit, 6-3 1/2" DC & 2 3/8" tbg. Do hard cmt from 3345-3401.
1-14-91 Do hard cmt from 3401-3550. Fall free. Pres tst squeeze to 500# for 15 min. Bleed off to 480# - OK.
1-15-91 Circ sand on RBP at 3595. Unable to rel RBP. Engage RBP at 3595 & jar for 3 hrs
1-21-91 Tag up at 3718 (2' above liner). Drill on junk for 1 hr. w/o making any hole. POH. Mill from 3718-3720. Fall free. GIH & tag up at 3869.
1-22-91 Pull above liner w/ tools. Mix & pump 5 sks of liner top for 30 min before falling free. GIH & tag up at 3831. Mill from 3831-3857.
1-23-91 Co metal scale from 3857-3920 (T.D.) GIH w/ 2 3/8" Sopma, SN & 117 jts 2 3/8" buttress tbg. nd BOP & land SA at 3791. GIH w/ 11" x 6" DT pmp, 151-3/4" rods (cont)

14. I hereby certify that the foregoing is true and correct

Signed Marionette Nelson Title Adm Date _____
(This space for Federal or State office use)

Approved by _____ Title _____ Date _____
Conditions of approval, if any: