## SUBMIT IN TRIPLICATE. (Other instructions on reverse side)

Form approved. Budget Bureau No. 42-R1425.

## UNITED STATES

DEPARTMENT OF THE INTERIORS IN 167						5. LEASE DESIGNATION AND SERIAL NO.	
GEOLOGICAL SURVEY						LC 031622 (b)/d	
APPLICATION	FOR PERMIT	TO DRILL, D	DEEPEN	, OR PLUG E	BACK	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
1a. TYPE OF WORK		DEEDEN!	_	DI 110 D.	au 🖼	7. UNIT AGREEMENT NAME	
DKI b. TYPE OF WELL	LL 🗆	DEEPEN [		PLUG BA	CK 🔯		
OIL THE GA	S OTHER		SINGL ZONE	MULTIP	LIB	NMFU 8, FARM OR LEASE NAME	
2. NAME OF OPERATOR	DIN CO VIRIS		ZUNE	ZUNE ZUNE		Sanderson AE-14	
Continental Oil Company						9, WELL NO.	
3. ADDRESS OF OPERATOR						1	
P. O. Box 460, Hobbs, New Mexico 88240 4. Location of Well (Report location clearly and in accordance with any State requirements.*)						10. FIBLD AND POOL. OB WILDCAT	
At surface 330! PMT, and $660!$ PWT. Soc. 1/1 $\pi$ 200 B 36E $\stackrel{\triangle}{=}$						Monument, G.S.A. Pool	
Lea County, New Mexico.						11. SEC., T., R., M., OR BLK AND SURVEY OR AREA	
						36	
Same 14. DISTANCE IN MILES AND DIRECTION FROM NEAREST TOWN OR POST OFFICE*						Sec. 14, T-20S, R-37E 12. COUNTY OR PARISH 13, STATE	
						1_	
15. DISTANCE FROM PROPO LOCATION TO NEAREST		1	16. No. o	F ACRES IN LEASE		OF ACRES ASSIGNED	
PROPERTY OR LEASE L (Also to nearest drig		TO T			HIS. WELL 40		
18. DISTANCE FROM PROPOSED LOCATION® TO NEAREST WELL, DRILLING, COMPLETED,			19. PROPOSED DEPTH 20. RO			RY OR CABLE TOOLS	
OR APPLIED FOR, ON THE	IS LEASE, FT.		3	7871			
21. ELEVATIONS (Show whe	-					22. APPROX. DATE WORK WILL START*	
23.	575' D.F.					7-14-67	
20.		PROPOSED CASIN	NG AND C	EMENTING PROGR.	AM		
SIZE OF HOLE	SIZE OF HOLE SIZE OF CASING WEIGHT P		FOOT SETTING DEPTH			QUANTITY OF CEMENT	
		···		·			
ابل	hr subject w	rell is nra	sentl	v producin	o an a	average of 23 BO, 3 BW,	
and 865 MCF	Cherday	orr ic pro	J D O 11 0 <b>2</b>	hreameri.	0 ~	2001456 01 25 20, 5 21,	
	c por day.						
						the Queen Zone and	
		ive Monume	ent G.	S.A., foll	owing	the procedure out-	
lined below	:						
7	Snot seme	nt on hot	tom ur	to 37871			
<ol> <li>Spot cement on bottom up to 3787'.</li> <li>Treat open hole section w/string shot. (3751'-3787').</li> </ol>							
2. Treat open hole section w/string shot. (3751'-3787'). 3. Acidize w/1500 gals. 15% LSTNE Acid.							
4. Place well on production.							
IN ABOVE SPACE DESCRIBE	PROPOSED PROGRAM: If	proposal is to deep	en or plug	back, give data on p	resent prod	luctive zone and proposed new productive d and true vertical depths. Give blowout	
preventer program, if any	y.	anij, give pertinent		ubsuitace locations a	по шеавите	a and true vertical depths. Give blowout	
24.	1)-1/1	•					
SIGNED TOUS	- DESTORY	TIT	L Supe	rvising En	ginee	r	
(This space for Feder	ral or State office use)				· · · · · · · · · · · · · · · · · · ·		
V To Italian	Ja omic omic use)					و مستور	
PERMIT NO.			API	PROVAL DATE	<del></del>	DOBOVEV	
A Man Ottale and					1	APPIN	
CONDITIONS OF APPROV	AT. TW ANY	TIT	LE		<del></del>	PATE 196	

\*See Instructions On Reverse Side

CHEV-Mid-2

PAN AM-Hobbs-2

USGS-5 ATL-Ros-2