

PLUGS AND ADAPTERS

Heaving plug—Material _____ Length _____ Depth set _____
 Adapters—Material _____ Size _____

SHOOTING RECORD

Size	Shell used	Explosive used	Quantity	Date	Depth shot	Depth cleaned out

TOOLS USED

Rotary tools were used from _____ feet to 3960 feet, and from _____ feet to _____ feet
 Cable tools were used from _____ feet to _____ feet, and from _____ feet to _____ feet

DATES

_____, 19____ Put to producing May 12, 1955
 The production for the first 24 hours was 136 barrels of fluid of which 100 % was oil; _____ %
 emulsion; _____ % water; and _____ % sediment. Gravity, °Bé. 31
 If gas well, cu. ft. per 24 hours _____ Gallons gasoline per 1,000 cu. ft. of gas _____
 Rock pressure, lbs. per sq. in. _____

EMPLOYEES

J. G. Cole, Driller J. W. Ellis, Driller
O. E. Kelton, Driller _____, Driller

FORMATION RECORD

FROM—	TO—	TOTAL FEET	FORMATION
0	190	190	Surface Sand
190	255	65	Redrock & Shells
255	330	75	Redbed
330	1190	860	Redbed & Shells
1190	1240	50	Redrock & Sand
1240	1340	100	Anhydrite
1340	2630	1290	Salt & Anhydrite
2630	2735	105	Gyp & Anhydrite
2735	2753	18	Gray Lime
2753	2789	36	Gyp & Anhydrite
2789	2950	161	Lime & Gyp
2950	3000	50	Sandy Lime & Sand
3000	3168	168	Sandy Lime
3168	3414	226	Lime
3414	3448	35	Lime and Gyp
3448	3481	33	Sandy Lime
3481	3500	19	Sandy Lime
3500	3543	43	Sandy Lime
3543	3681	138	Sandy Lime
3681	3700	19	Sandy Lime
3700	3810	110	Sandy Lime
3810	3860	50	Sandy Lime

ILLEGIBLE

FORMATION RECORD—Continued