

LEASE L. W. White A

WELL NO. 6 POOL E. ice

JOB Plug + Abandon

LOCATION 1980' FS + EL, Sec 25-20s-36E, Lea Co. C.C.

H = KDB to CSg = 13'

COMPLETED 7-1-65

IP "F" 496 BOPD, 08W

PRESENT STATUS CI

SUGGESTED PROCEDURE

10 $\frac{3}{4}$ " 32.75# L.W.
CSg set @ 254' w/175 SX

7 $\frac{1}{2}$ " 26.4# L.W. CSg
Set @ 1090' w/320 SX

2 $\frac{3}{8}$ " 4.7# H-HO, 10V, EVE,
Tbg set @ 3829' w/BPOB
+ SN @ 3814'

1. Pull Tbg
2. Run CIBP on Tbg + set @ 3700'
3. Circ. hole w/mud
4. Spot cmt plug over BP (10 SX)
5. Pull Tbg to 50'
6. Spot surface plug (7 SX)
7. set marker + clear location

5 $\frac{1}{2}$ " 17# LW + Smls CSg
Set @ 3720' w/150 SX

4 $\frac{1}{4}$ " O.H.

TD 3850

JLT

12-16-65