STATE OF NEW MEXICO NERGY AND MINERALS DEPARTMENT

and this will territed Of		
	1	
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.	1	
LANG OFFICE	1	
OPERATOR	1	

NDITIONS OF APPROVAL, IF ANY:

OIL CONSERVATION DIVISION

DISTRIBUTION		1011 21 4131014	_
SANTA FE			Form C-103 Revised 10-1-78
FILE	SANTA FE, NEW M	IEXICO 87501	wes.1264 th-1-19
U.S.G.S.			5a. Indicate Type of Lease
LANO OFFICE		·	State Federal Fee
OPERATOR		•	
			5. State Oil & Gas Lease No.
SHUDDA	() () () () () () () () () ()		
SUNUK' (DO NOT USE THIS FORM FOR PROP	Y NOTICES AND REPORTS ON WE POSALS TO DRILL OR TO DEEPEN OR PLUG BACK ON FOR FERMIT - " (FORM C-101) FOR SUCH PI	LLS	
USE "APPLICATI	DN FOR PERMIT -" (FORM C-101) FOR SUCH P	TO A DIFFERENT RESERVOIR. ROPOSALS.)	
OIL GAS			7. Unit Agreement Name
well well	OTHER- Injector		
Name of Operator	111100001		Eunice Monument South Un
Chevron U.S.A. Inc		·	8. Farm or Lease Name
Address of Operator			
D O D 670			9. Well No.
P.O. Box 670 , Ho	<u>bbs, NM 88240</u>		108
			10 Field and Bool or Wild-
unit Letten G 19	180 FEET FROM THE North	1020	Tundas Maria de 0.404
•	THE THOM THE THOSE OFF	LINE AND PEET FR	Eunice Monument G/SA
Fast	25 200	0.57	
THE LINE, SECTION	25 TOWNSHIP 20S	RANGE 36ENMP	~ ((((((((((((((((((((((((((((((((((((
mmmmmm			
	15. Elevation (Show whether DF,	RT, GR, etc.)	12. County
	3535'		Lea
Check A	Decoriora Pou Ta I-1:		
Circle A	ppropriate Box To Indicate Natu	ire of Notice, Report or C	ther Data
NOTICE OF IN	TENTION TO:	SUBSEQUE	T REPORT OF:
	1.		
ERFORM REMEDIAL WORK	PLUG AND ABANDON RE	MEDIAL WORK	
EMPORARILY ABANDON		IMMENCE DRILLING OPHS.	ALTERING CASING
ULL OR ALTER CASING		;= =<	PLUG AND ABANDONMENT
· · · ·	CA CA	SING TEST AND CEMENT JOB	· _
orus Doopon log ponf ac	da	OTHER	
OTHER Deepen, log, perf, ac	dz, conv. to inj [x]		
7. Describe Proposed or Completed One	rations (Clearly state all services decided		
work) SEE RULE 1103.	(etait, state all pertinent detaits,	and give pertinent dates, includin	ig estimated date of starting any proposed
·			·
It is proposed to	deepen the subject well, f	rom 3250! to 3010!	log mane
at recommended into	ervals, acidize and equip	for in in it.	Log, perf
and tubing to 600n	ci for 20 min Date	for injection. Test	casing,packer,
and capting to boop	si for 30 min. Return to	production as injecto	or.
	• •		
			·
		•	•
•			
	•		•
·			
	•		1
		2421	
I hereby certify that the information of	ove is true and complete to the best of my		
-,, w the manifeston as	ore as true and complete to the best of my	knowledge and belief.	
$m \in \mathcal{A}$			
m. E. a.	Bush Ctaff	Duilling Faci	
		Drilling Engineer	<u>5-5-87</u>
ORIGINAL SIGNED BY JER			
DISTRICT I SUPERV	ક્યાં		MAY A MAS
40VED BY	TITLE		MAY 7 1987
			- · · · · ·