

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-04350
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-2204
7. Lease Name or Unit Agreement Name	NEW
8. Well No.	1
9. Pool name or Wildcat	EUMONT YATES 7R QUEEN

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Phillips Petroleum Company	
3. Address of Operator 4001 Penbrook Street, Odessa, TX 79762	
4. Well Location Unit Letter <u>A</u> : <u>660</u> Feet From The <u>NORTH</u> Line and <u>330</u> Feet From The <u>EAST</u> Line	
Section <u>26</u> Township <u>20 S</u> Range <u>36 E</u> NMPM <u>LEA</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3554' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: PERFORATED & TESTED THE QUEEN ZONE ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1/20/95 RU DDU. COOH AND LAY DOWN ALL PRODUCTION EQUIPMENT.
1/21/95 SET CIBP AT 3690'. GIH W/2-3/8" TBG AND PACKER. SET PACKER AT 3680'.
1/24/95 GIH W/TBG AND PKR AND SET AT 3680'. TEST CIBP TO 500# OK. COOH. GIH W/4" CSG GUN AND PERFORATE THE QUEEN FORMATION 3596'-3683' W/75 SHOTS. DUMP 1 SX CMT ON TOP OF CIBP. NEW PBTD @3685'. GIH W/TBG AND PKR TO 3545'. SET PKR AT 3545'. SET PKR AT 3545'. ND BOP AND NU WELL HEAD. SWAB.
1/25/95 ACIDIZED W/4000 GALS OF 7-1/2% HCL.
1/26/95 BUILD UP 50# PRESSURE. SHUT WELL IN AND RD MO DDU.
3/10/95 RU DDU. COOH AND LAY DOWN ALL TBG. RD DDU.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders

TITLE SUPERVISOR, REG. AFFAIRS DATE 3/17/95

TYPE OR PRINT NAME L. M. SANDERS

TELEPHONE NO. 915/368-1488

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

MAR 22 1995

APPROVED BY _____

TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

mfp