## NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

## MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well

	Indicate Nature of Rep	ort by Checkin	ng Belo	W	
REPORT ON BEGINNING DRILLING OPERATIONS	REPORT ON RESU OF CASING SHUT	LT OF TEST OFF	X	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL	REPORT ON RECO	MPLETION		REPORT ON (Other) completic	x ac
	6-30-1	55		Arte	Sia (Place)
Following is a report on the work don					(a face)
Charm Oil Company (Company or Operator)		Coll (Lease)			
Gackle Drlg. Co (Contractor)	) •	, Well No2		in the <b>SE</b> 1/4 <b>SE</b> 1/4	4 of Sec <b>33</b>
T20, R36, NMPM.,	Eumont	Pool,		Lea	County
The Dates of this work were as folows:	June 27	thru 30	***********		
Nation of intension to Just 1000 1000					
Notice of intention to do the work (was) (was	is not) submitted on Form	C-102 on	(C	ross out incorrect words)	19
m	<b>-1</b>			'S OBTAINED	
Drilled to 3880'. Ran regular. Drilled cement ou Sand oiled with 10,000 gall	it to 3875. Ran G	at 3880 as	nd ce	mented with 400 sac perforated from 385	2 - 680.
regular. Drilled cement ou	t to 3875. Ran G	at 3880 as	nd ce	mented with 400 sac perforated from 385	2 - 680.
regular. Drilled cement on Sand oiled with 10,000 gall	t to 3875. Ran G	at 3880 as leasant ron land 20,000	od cellog, Dibs	mented with 400 sac perforated from 385 . send. Put on pro	2 - 680. duction.
Witnessed by	t to 3875. Ran G	at 3880 as and 20,000	y that t	mented with 400 sac perforated from 385 . sand. Put on pro	2 - 680. duction.
Witnessed by	t to 3875. Ran G	at 3880 as and 20,000	y that t	mented with 400 sac perforated from 385 . send. Put on pro	2 - 680. duction.

Address.....