

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO. 30-025-04392

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:
STATE WE "G"

8. Well No. 1

9. Pool name or Wildcat
Eumont; Yates-7RVRS-Queen (Oil)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☒ Other

2. Name of Operator
ERWIN OIL & GAS, LTD. CO.

3. Address of Operator
PO BOX 1506 HOBBS NM 88241

4. Well Location
Unit Letter H : feet from the line and feet from the line
Section 34 Township 20S Range 36E NMPM County Lea


10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1) Set CIBP @ 3475' place 35' of cement on top-tag
2) Set Plug @ 31610' 25SX5 OR 100' WHICHEVER GREATER
3) PERFORATE @ 295' 342' SQUEEZE 50' CEMENT OUT AND 50' INSIDE CASING.
4) 60' SURFACE PLUG.
5) 9.5 lbs SALT MUD IN between plugs.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE Ralph E. Erwin TITLE OWNER DATE 12-22-02

Type or print name Ralph E. Erwin Telephone No. (505) 393-3648
(This space for State use)

APPROVED BY _____ TITLE MANAGER DATE JAN 24 2002
Conditions of approval, if any:

THE COMMISSIONER HAS BEEN NOTIFIED 24 HOURS BEFORE THE BEGINNING OF THE PERIOD FOR WHICH THE PERMIT IS GRANTED.

J
C