STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

•• • • • • • • • • • • • • • • • • • • •	
C-818 #UT	C = 1 1
SANTA FE	
FILE	
U 0.0.a.	
LAND CIPICS	
TRANSPORTER	CIL
	DAG
CPERATOR	
PROMATION CFF	MC E

OIL CONSERVATION DIVISION P. O. BOX 2088 'SANTA FE, NEW MEXICO 87501

Form C-104 Reviseo 10-01-78 Format 05-01-83 Page 1

REQUEST FOR ALLOWABLE AND AUTHORIZATION TO TRANSPORT OIL AND NATURAL GAS

1.	AUTHORI	ZATIONIT	O TRANS	PORT OIL	L AND NATU	RAL GAS	
C:* Texaco Producing Inc.							
Address							
PO Box 728, Hobbs, New	Mexico	88240					
Reason(s) for filing (Check proper box)					Other (Pleas	e explain)	
New Vell	Change in	Tronsporter	of:				
Recompletion	× 011			TY Gos			
Charge in Overership	Casin	gheod Gas	7	ondensate			
If change of ownership give name					.1		
and address of previous owner							
II. DESCRIPTION OF WELL AND I	LEASE			•			
Lease Name		Pool Name,	Including F	ormation		Kind of Lease	,
East Eumont Unit	12	Eumont	Yates	7-River	s Queen	State. Federal or Fee	Lecse No.
Location				, 1,1,0,1	5 Queen	FEE	
Unit Letter;;	Feet From	The No	cth Li	ne and 2	2400.4	Feet From The West	
4	100					u .	
Line of Section 4 Towns	hip 19S		Range	37E	, NMPN	. Lea	County
III. DESIGNATION OF TRANSPOR	TED OF O	II ANION					_
Name of Authorized Transporter of CII	or Co	ndensate [NATUKA.	L GAS	(6		
Texas New Mexico Pipeli		0055-195	ر ۱۲۱			to which approved copy of this form is	
Name of Authorized Transporter of Casing	tod Gas (X)	or Dry C		PO B	(C) 2528,	Hobbs, New Mexico 8824	0
Warren Petroleum Corp	. –					Tulsa, OK 74102	10 be sentj
If well produces oil or liquids.	nii Sec.	Twp.	Rge.		tually connect		
give location of tanks.	1		•			, men	•
If this production is commingled with t	hat from any	other less	e or pool.	give com	mingling orde	t number	
NOTE: Complete Parts IV and V o				•	and the contract	. Humber.	
		te ij neces	sary.				
VI. CERTIFICATE OF COMPLIANC	E				OIL C	ONSERVATION DIVISION	
I hereby certify that the rules and regulations	of the Oil Cor	servation Di	vision have	APPR	OVED		
been complied with and that the information gi my knowledge and belief.	iven is true and	l complete to	the best of				. 19
, and an age 272 oct			•	BY	<u></u>	SHIAL SEGNED BY JERRY SEXTO	<u>N</u>
·				TITLE	•	March 198 Jan 1994	1
1 /	\supset			11			
Allean	/			1	is form is to	be filed in compliance with AUL	£ 1104.
Area Superintendent	,	397-3	571])	nie iom musi	cest for allowable for a newly drill the accompanied by a tabulation well in accordance with AULE 11	ad 16 a danstage - a
7-25-88				Al able or	l sections of new and re-	this form must be filled out completed wells.	etely for allow-
(Daie)					n.e or number	ections I. II. III. and VI for than, or transporter, or other such than.	er of condition.
			.	Se	parate Forma ted wella.	C-104 must be filed for each p	col in multiply

		O11 Well	Gas Well	Now Well	WOLFOAGE	Deepen	Piug Bock	Same Restv.	
Designate Type of Completion	on - (X)	• • •	1 1		1 1 .1	! ! 	+	1	<u> </u>
Date Spudded	Date Compl. Ready to Prod.		Total Dept	Total Depth			P.B.T.D.		
Elevations (DF, RKB, RT, GR, etc.,	Name of Producing Formation			Top Oil/Gas Pay			Tubing Depth		
							Depth Casing Shoe		
Perforations	_								
		TUBING,	CASING, AI	ID CEMENT	ING RECOR	D			
HOLE SIZE	CASI	NG & TUB			DEPTH SE		<u>S</u>	ACKS CEME	NT
	<u></u>								
v. TEST DATA AND REQUEST	FOR ALLC)WABLE	(Test must be able for this	after recovery	y of total volu r full 24 hours	ime of load o	ll and must be	equal to or exc	and top bild
V. TEST DATA AND REQUEST OH. WELL. Date Fire New Oil Bun To Tanks	FOR ALLO		(Test must be able for this	after recovery depth or be fo	y of total volu full 24 hours Method (Flow	ime of load o	il and must be	equal to or exc	eed top bild
OH, WELL		• ((Test must be able for this	ofter recovery depth or be fo Producing Casing Pi	Method (Flou	ume of load o	ll and must be lift, etc.)		eed top bild
Date Fire New Oll Run To Tanks	Date of Te	• ((Test must be able for this	Producing	Method (Flou	ume of load o	lift, etc.)	•	eed top blic
Off. WELL. Date Fire' New Oil Run To Tanks Long.h of Test	Date of Te	• ((Test must be able for this	Producing Casing Pi	Method (Flou	ume of load o	Choke Siz	•	eed top blio
Off. Well. Date Fire New Oil Run To Tanks Long.h of Test Actual Prod. During Test	Date of Te	• ((Test must be able for this	Casing Pr	Method (Flou	и, ритр, дая	Choxe Siz	•	eed top bilo
Off. WELL. Date Fire' New Oil Run To Tanks Long.h of Test	Date of Te	et saure	(Test must be able for this	Casing Pr	Method (Flou	и, ритр, дая	Choxe Siz	•	eed top blic