

## U. S. GEOLOGICAL SURVEY COMMISSION

P. O. BOX 1850

ROSWELL, NEW MEXICO 88240

0+5 - USGS - P.O. Box 1857

1 - Engr. LM

1 - Laura Richardson-Midland

Form 9-331  
Dec. 1973

Roswell, NM 88201

1 - Foreman EF

1 - File Form Approved.

Budget Bureau No. 42-R1424

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☐ other NIO well  
well well

## 2. NAME OF OPERATOR

Getty Oil Company

## 3. ADDRESS OF OPERATOR

P.O. Box 730 Hobbs, NM 88240

## 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 660' FNL &amp; 660' FEL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

## 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

## REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐CHANGE ZONES ☐ABANDON\* ☐(other) Test casing ☐

## SUBSEQUENT REPORT OF:

☐☐☐☐☐☐☐☐

## 5. LEASE

NM 02053

## 6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## 7. UNIT AGREEMENT NAME

East Eumont Unit

## 8. FARM OR LEASE NAME

## 9. WELL NO.

E 14

## 10. FIELD OR WILDCAT NAME

Eumont

## 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 4, T19S, R37E

## 12. COUNTY OR PARISH

Lea

## 13. STATE

NM

## 14. API NO.

## 15. ELEVATIONS (SHOW DF, KDB, AND WD)

3701' DF

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

## 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. TIH w/4 1/2" packer.
2. Set packer + 3800', pressure test annulus to 1000#.
3. If pressure does not hold, locate leak w/RBP and pkr.
4. Squeeze leak with class "C" cement.
5. TOH w/pkr. WOC.
6. Drill out cement.
7. Continue to test casing until all leaks are repaired.
8. TOH w/RBP and pkr.
9. Rig down. Well will remain TA.

RECEIVED

MAR 9 1983

Subsurface Safety Valve: Manu. and Type

Set @ Ft.

## 18. I hereby certify that the foregoing is true and correct

SIGNED

Date R. Crockett

TITLE Area Superintendent

DATE

OIL &amp; GAS

MINERALS MGMT. SERVICE  
ROSWELL, NEW MEXICOAPPROVED  
(Orig. Sgd.) PETER W. CHESTER

APPROVED BY

TITLE

DATE

MAR 10 1983

FOR

JAMES A. GILLHAM  
DISTRICT SUPERVISOR

\*See Instructions on Reverse Side

T.A. APPROVED  
END  
PERIOD  
MAR 10 1984