O, C COPIES RECEIVED	Form C-103 Supersedes Old				
DISTRIBUTION NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65				
	Sa. Indicate Type of Lease				
U.S.G.S.	5. State Oil & Gas Lease No.				
OPERATOR	<b>E-32</b> 89				
	THUNNING THUNNING				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OF FORDER OF PLUG BACK TO A DIFFERENT RESERVOIR.					
USE "APPLICATION FOR PERMIT = (TORM 2 TOT)	7. Unit Agreement Name				
1. OIL GAS WELL WELL OTHER.					
	8. Farm of Lease Name				
TEXACO Inc.	N.M.'CE' State NCT-1				
	2				
P. O. Box 728 - Hobbs, New Mexico 88240	10. Field and Pool, or Wildcat				
4. Location of Well UNIT LETTER F 1685 FEET FROM THE North LINE AND 1652 FEET FROM	Eumont Queen (Gas)				
Heat 6 198 and 37E MMPM.					
	12. County				
15. Elevation (Show whether DF, RT, GR, etc.)	Lea				
3730' GR					
16. Check Appropriate Box To Indicate Nature of Notice, Report or Ot	T REPORT OF:				
NOTICE OF INTENTION TO: SUBSEQUEN					
PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING				
PERFORM REMEDIAL WORK	PLUG AND ABANDONMENT				
TEMPORARILY ABANDON CASING TEST AND CEMENT JQB					
PULL OR ALTER CASING OTHER Recomplete in	Eumont Gas Zone AA				
OTHER					
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includin	g estimated date of starting any proposed				
work) SEE RULE 1103.					
1. Pulled rods and tubing.					
<ol> <li>Pulled rods and tubing.</li> <li>Ran 2-3/8" tubing w/casing scraper &amp; bit to 3945'. Plugged back w/20/40 sand from 3945-3923. Pulled tubing, casing scraper and bit.</li> </ol>					
sand from 3945-3925. Fulled tubing. 3. Ran tubing, tagged sand fill @ 3915. Pulled tubing. 3. Ran tubing, tagged sand fill @ 3915. Pulled tubing.					
<ol> <li>Ran tubing, tagged sand fill @ 3915. Purled tubing.</li> <li>Ran tubing, tagged sand fill @ 3915. Purled tubing.</li> <li>Perforated 4-1/2" casing w/2 JSPI @ 3790,99, 3813, 25, 40, 74, 91, &amp; 3911'.</li> <li>Perforated 4-1/2" casing w/2 JSPI @ 3790,99, 3813, 25, 40, 74, 91, &amp; 3911'.</li> </ol>					
5. Ran 2-3/8" tubing w/packer and boards the garder @ 3754'. across perforations 3790-3911. Set packer @ 3754'.					
across perforations 3790-3911. Set packer & 5754 6. Acidized perforations w/1200 gals. 15% Unisol acid in 3-400 gal. stages 6. Acidized perforations w/1200 gals. 15% Unisol acid in 3-400 gal. stages					
maine 16 hall gasiers. LOADED diffution of marine to the					
7. Dropped 4 foam sticks in noise. Swabbed rol log HCL FF acid.					
	d - 011) June 25,				
9. Swab, workover unsuccessiul, in-o (10 be necessiul)					
1974.					
the to the best of my knowledge and belief.					
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
TITLE Asst. Dist. Supt.					
SIGNED					

U		Orial Started by		DATE
APPROVED BY		<u>Jee P. Pamey</u> Diale, 1, Supv.	TITLE	
CONDITIONS OF APP	ROVAL, IF ANY;	• • تإمات وغد وبالساسي		